



SERVICE BULLETIN

from: TRIO-KENWOOD COMMUNICATIONS, INC.

TS-180S

#803

SUBJECT: TS-180S CW DELAY DURING VOX MEMORY OPERATION

DATE 2/7/80

Some operators may report missing the first "dit" during CW VOX operation on the memories. This will occur only in early units, and may be improved by changing one capacitor in the DFC.

On the DFC VCO unit X50-1550-00, check C3 at the base of Q3. If C3 is a 22uF electrolytic, change to a .01uF disc. No adjustments are necessary.

JEB/yn