

APPENDIX A. RUNNING DESIGN CHANGES/FIELD SERVICE BULLETINS

The factory provided these ten Field Service Bulletins to 8X32 dealers and customers. Each Bulletin describes a remedial procedure for a specific problem, or a hardware change necessary to implement an improvement in the machine's design.

Bulletin # 1 - Panel Board Connector

Bulletin # 2 - Level Functions

Bulletin # 3 - Wrong Value R26

Bulletin # 4 - Keystone Bracket

Bulletin # 5 - 7.5V Transformer Wiring Error

Bulletin # 6 - Potential -15V Supply Intermittent

Bulletin # 7 - "Buzz Saw" Noise

Bulletin # 8 - CFD Gain Error

Bulletin # 9 - Program Update, Edition E4-0 to Edition E4-1

Bulletin #10 - Lowering the Noise Level

URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #1

1981 October 6

TITLE: PANEL BOARD CONNECTOR

Page 1 of 2

UNITS AFFECTED: 8X32's with serial number 1-521 and under shipped before October 6, 1981 may have this problem. After October 6, 1981, units will not have this problem.


PROBLEM: J5 DIP connector from panel board to CPU board may vibrate loose in shipping, resulting in failure of front panel display or control functions.

WHEN TO CORRECT PROBLEM: Certainly make the changes if you find that the connector has worked loose in a particular unit, or if the unit will be shipped or transported very much. If the unit is simply going to be used in a relatively fixed installation, just let well enough alone. Not all the units had the cable under sufficient stress so that this would be a problem.


HOW TO CORRECT THE PROBLEM: Unplug the unit from power. Set it right side up with front panel facing you. Protect the front panel with a soft cloth. Remove the top cover with the screws around the perimeter. Locate the ribbon cable at the front left of the unit and unplug the 24 Pin plug from J5 on the CPU-1 PC board. Gently bend it back, out of the way, toward the front of the unit and locate the tie wrap securing the large bundle of 6 wires passing underneath the cable, and cut the tie wrap securing these wires to the mother board. Redress that 6 wire group so that the wires are underneath the mother board and out of the way completely of the ribbon cable as it passes toward J5. Using a file, put 2 small notches (roughly 3/16" wide by 1/32" deep) 1 at each end of the plug that goes into J5. Attach the short piece of foam tape on top of the plug that goes into J5. Reinstall the plug into J5 and snap the new plastic clip down in place to secure the connector. Screw the cover back in place.

REQUIRED MATERIALS:

- 1.) 1 piece foam self stick tape, 1/2" x 3/4" x 1/8".
- 2.) 1 eby 24 Pin DIP clamp.




24 Pin DIP clamp



1/2" x 3/4" x 1/8" foam tape

remove protective paper



plug from panel for CPU-1, J5

URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #2

1981 October 6

TITLE: LEVEL FUNCTIONS

Page 1 of 3

UNITS AFFECTED: 8X32's with serial number 1-521 and under shipped before October 6, 1981 will have this error. Units leaving the factory later than October 6, 1981 will not have this problem.

PROBLEM: SIP resistor network RN34 on ANA-2 PC board has its pin 1 connected in error to +5V. It should be connected to +7.5V. This may result in premature failure of IC's U2, U4, U5, and U6. These are Fairchild or Motorola MC14051B CMOS IC's.

The symptom would be improper operation of the early reflection level controls and/or initial reverberation level controls. Improper operation could take the form of the levels not changing equally in both channels, or not changing smoothly in monotonically increasing or decreasing steps. Another symptom could be pops or clicks as the level is nudged up or down.


WHEN TO CORRECT PROBLEM: If the unit develops these problems, and U2, U4, U5 or U6 has failed. If the unit is back in-house for service at any time and it is convenient, do the ECO. Otherwise, if the unit is in the hands of a customer, wait and see if a problem develops.

HOW TO CORRECT THE PROBLEM: Disconnect the 8X32 from power. Turn it upside down, with the front panel facing you. Protect the front panel with a soft cloth. Remove the screws holding the bottom cover in place and set the bottom cover aside. Unplug the 2 input connectors, the connector from the potentiometer on the rear panel and connectors going to the output connectors on the front left side. Unsolder the 3 green wires, having made a note in advance where they were soldered. Remove five number 6-32 screws around the perimeter of the board. DO NOT remove the 2 screws at the very front edge of the board. Remove the 3 hexagonal standoffs. Carefully bend the wires out of the way at the left rear, and hinge the analog board upward. Locate resistor network RN34, near IC65 and, on the etch side of the board (the

solder side, the side without components), find Pin 1 (noted by a square pad) of RN34. With a sharp knife cut the edge going to Pin 1 of RN34. Referring to the attached diagram, run a small insulated wire from RN34, Pin 1 to the pad near RN36 Pin 1. Verify with an ohm meter that this RN34 Pin 1 is now connected to +7.5V and not to +5V. If the unit had developed a problem leading to carrying out this change, locate the defective IC U2, U4, U5 or U6 by normal trouble shooting techniques and replace as necessary.

REQUIRED MATERIALS:

- 1.) 2 IC's, MC14051B or equivalent



URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #3

1981 December 3


TITLE: WRONG VALUE R26

Page 1 of 3

UNITS AFFECTED: 8X32's with serial number 1-523 through 1-530.

PROBLEM: It has been discovered that a few URSA MAJOR 8X32's may have been shipped with a resistor of the wrong value. The unit should probably still function properly, but under severe heat stress it could blow the resistor and this would shut down the memory.

To avoid this failure, we ask if you would please check the resistor in question - R26. This resistor is the voltage dropping resistor in series with zener diode D17. The resistor should be of value 270Ω $\frac{1}{2}$ watt. The color code for this value is red, purple, brown, gold. Some units may have a 27Ω $\frac{1}{2}$ watt resistor with color code red, purple, black, and gold. The circuit looks like this:



The resistor can be checked without removing the cover by shining a bright light through the top cover vent holes, and viewing R26. Please find enclosed a copy of the printed circuit board layout. This picture identifies the resistor.

It is important to make a positive identification of the brown stripe, since the wrong resistor runs the zener diode at ten times its normal current. If you must, remove the top cover to see, for certain, that it is 270Ω .

HOW TO CORRECT THE PROBLEM: If it is the wrong resistor:

- 1). Remove the top cover.
- 2). Carefully unsolder the resistor from the top side.
- 3). If necessary, use a solder sucker to carefully remove old solder.
- 4). Replace with new resistor (also enclosed) of value 270Ω $\frac{1}{2}$ watt.

URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #4

1981 September 28

TITLE: KEYSTONE BRACKET


Page 1 of 1

UNITS AFFECTED: 8X32's with Serial Number 1-545 and under may have this characteristic.

PROBLEM: The Keystone bracket which is mounted on chassis under H17 of ANA-2, sometimes makes contact with R13 of ANA-2.

WHEN TO CORRECT PROBLEM: Although some units may have left the factory with this characteristic, none were shorting at time of shipment, or the symptom--severe hum and noise and loss of signal in one channel--would have been picked up. It is unlikely that shipping would vibrate the PC board into a new position shorting R13, but if the 8X32 will be on the road, in a van, or touring, it would be good insurance to check for the bracket and correct if it wasn't trimmed.

HOW TO CORRECT THE PROBLEM: Remove AC power and then the bottom cover. Unsolder 3 green wires from connector on ANA. Remove all plug-in connectors from the ANA, except the 3 ribbon cables. Remove 3 standoffs and the perimeter screws, except for the two at the front edge of the ANA. Hinge the board up to reveal the bracket closest to R13. Refer to the figure and clip the bracket.



Authors of ECO: Ronald A. Blomberg, Christopher Moore

URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #5

1981 September 14

TITLE: 7.5V TRANSFORMER WIRING ERROR

UNITS AFFECTED: 8X32's shipped before roughly September 14, 1981 may have this problem. A factory alert was sent out and we believe most units were identified and corrected in the field.

PROBLEM: Units hot to touch on chassis, right hand side. The extra heat is due to a wiring error where the blue-yellow and one of the blue wires were interchanged coming from the transformer secondary.

WHEN TO CORRECT PROBLEM: If the unit seems to be running hot on the right hand side panel, look inside to see if the problem exists. Peer through the top cover right hand side and find PC pads 13, 14 & 15. Number 15 should have a blue-yellow wire. 13 and 14 should have blue wires.


HOW TO CORRECT THE PROBLEM: Unplug the 8X32 from A/C line. Remove the top cover. Find the blue-yellow wire in the wrong hole. Unsolder the blue-yellow wire from the top side, applying heat to the joint and pulling the wire upward. Also remove the blue wire in hole 15. Reinsert the blue-yellow wire in hole 14 and resolder from the top.

REQUIRED MATERIALS: Solder

COMMENT: In practice, operating the unit without correcting this problem will not lead to field failure. There is enough thermal safety margin in the chassis and in the regulator.

BLU-YEL wire should go here, in 15.

AUTHOR: Christopher Moore



URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #6

1982 January 10
Page 1 of 2

TITLE: POTENTIAL -15V SUPPLY INTERMITTENT

UNITS AFFECTED: 8X32's with serial numbers 536 and under all have a potential for this problem. A few units with serial numbers between 544 and 538 may also have the potential for this problem. Units with serial number 545 and greater will not have this problem. Units shipped after January 11, 1982 will not have this problem.


PROBLEM: The negative lead for capacitor C26 on the mother board (MOM) passes through a hole that is not plated through. Without the plating there is a slight chance that a connection does not exist or could become intermittent from the etch side of the PC board to the component side. In the event that this connection did become intermittent, the -15V power supply would drop to 0. This would result in failure of the audio and other functions of the 8X32.

WHEN TO CORRECT PROBLEM: This is only a potential problem. We know that at the time each 8X32 left the factory, this problem did not exist. Furthermore, each unit is subjected to a mechanical shock test to look for intermittents. We would recommend carrying out this change if a unit is in for other service and the ANA board has to be disassembled for some other reason. Another instance in which it would be good to carry out this correction, would be for 8X32's that are going to travel on the road, in vans or on tour and be subjected to a lot of vibration. Otherwise, we do not feel it is important to recall units and carry out the change.

HOW TO CORRECT PROBLEM: Remove the A/C line cord from the unit. Turn the 8X32 upside down and remove the bottom cover. Remove all the connectors going to the ANA board except the ribbon cables on the front edge. Unsolder the three green wires going to the connector on the ANA board. Remove the three hexagonal standoffs and all the small screws holding the ANA board down except the two at the front of the board. Swivel the analog board upware, revealing the underside of the MOM board, (the "etch side"). Locate C26 minus pad on the etch side of the board and D25 anode on the MOM board by observing from the component side. Solder a short piece of #22 insulated wire from C26 minus lead to D25 anode. Reassemble the unit. It would be wise to verify correct -15V power supply operation before completely reassembling the unit.

REQUIRED MATERIALS: Short length #22 wire.

FIGURE:



URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN # 7

1982 January 11
Page 1 of 3

TITLE: "BUZZ SAW" NOISE

UNITS AFFECTED: It is necessary to distinguish between three groups of units. As of this date, two units, serial numbers 537 and 545 have been corrected and no further attention is necessary. Six other units, Serial numbers 522, 529, 540, 541, 544 and 547 have been shipped with a partial execution of this correction. The third group, (which includes all other units with serial number 546 and lower), has had no corrective changes performed for this problem.

PROBLEM: In some units, the minor DC offsets inevitable associated with linear and A to D components, resulted in the A to D converter for the Ap signal resting with 0 signal at the decision point for mid scale, (the sign decision point). Normal circuit noise under these conditions will permit the build up of a hollow, reedy sounding noise in this converter which would appear at the output. This sounds sort of like a "buzz saw".

WHEN TO CORRECT PROBLEM: We distinguish two sets of units here. The six units that have a partial execution of the change, should, at the next opportunity for normal servicing on those units, have the rest of the change carried out. These have a 3dB greater internal sensitivity for the reverberator. In practice, this will not be noticed by the end user but it would be good to get in and make the change to fix it.

The second and larger group of units that have not had any work done to correct this problem, should really be left alone unless they have buzz saw noise and the end user has commented on it. In fact, all those units passed the factory QC and may very well not exhibit the problem due to the possibility that the DC offsets add up to a high enough voltage to keep the converter from the sign decision point.

HOW TO CORRECT PROBLEM: Remove the A/C line cord. Turn the 8X32 upside down. Remove the bottom cover. Unsolder the three green wires going to the connector on the ANA. Remove the other molex connectors coming from the back panel connectors and the potentiometer. Remove the three hexagonal standoffs and all the black screws holding the

board down except for the two at the front. Swivel the ANA board back revealing the etch side.

If this is one of the six units in the field that has the correction partially carried out, only do the steps that follow. On the component side, locate RN29 and RN28. These are two resistor networks located near U68. On the component side observe a fine etch running between RN28, pin 5 and RN29, pin 4. With a sharp exacto knife, cut that etch. Now, on the component side, take a small piece of #30 solid wire and solder a connection between RN28, pin 5 and U68, pin 3 nearby.

Go on to these steps if the unit is from the larger group of 8X32's that have not had any of these changes carried out at the factory.

Find a connection on the etch side from RN29, pin 4 to ground. Cut that connection. On the etch side, solder a short piece of wire from RN29, pin 4 to RN29, pin 3 (bare #30 wire is ok).


Using #30 insulated wire, connect RN29, pin 5 to RN19, pin 7 some distance away. Put the wire on the etch side of the board.

After making these changes, it is necessary to readjust RV4 on the ANA board. You will need an oscilloscope with an input sensitivity of at least 10mV per division to perform this adjustment. Connect a lead from MOM board U28, pin 15 (test signal NTLB) to the oscilloscope external trigger input and adjust the scope to trigger at roughly 5 microseconds per division sweep speed. Connect the oscilloscope vertical input probe to RN14, pin 5 on the ANA board. Set the 8X32 to a decay time of 0.0 seconds in any program. Observe a negative voltage on the oscilloscope face, probably with a pedestal; (that is looking like a square wave with a lot of fuzz and noise). If the difference between the two pedestal heights is more than about 5mV, swap a TLO74 or TLO84 op amp from positions U19, 21, 25, 27, etc. into position U63 until the step difference on the oscilloscope is 5mV or less. Now, use the adjustment potentiometer on the ANA board RV4 to adjust for a DC level on the oscilloscope of between -10 and -30mV, preferably around -20mV.


If you had to swap another TLO74 or TLO84 into position U63 in the prior paragraph, you must readjust RV3 also. Move the scope vertical input probe to RN15, pin 11 and adjust for -20mV on the portion of the pedestal waveform that moves in response to the adjustment. Resecure the ANA board and return the covers to the unit. That completes the change.

ETCH SIDE VIEW

COMPONENT SIDE VIEW



cut etch "X"
add 3 jumpers



REQUIRED MATERIALS: Solder
#30 insulated solid wire
Oscilloscope 10mV per division sensitivity, external
sync capability

AUTHOR: Christopher Moore

URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #8

1982 January 11
Page 1 of 2

TITLE: CFD GAIN ERROR

UNITS AFFECTED: This error has been corrected in units with serial numbers 537 and 545 and all other units shipped after 10 January 1982. The problem has not been corrected in any unit with serial number 547 or below shipped before 11 January 1982.

PROBLEM: There is a 3DB gain error in the contribution of three signals going into the reverberator output due to an error failing to ground two resistors.


WHEN TO CORRECT PROBLEM: The change in sound quality due to this error is extremely minor. It would probably be very difficult to detect it even under a direct AB comparison. Therefore, do not go to any trouble to correct this problem unless a unit is inhouse and disassembled to the point where the under side of the ANA board is accessible.

HOW TO CORRECT PROBLEM: Unplug the power cord. Turn the 8X32 upside down. Remove the bottom cover. Unsolder the three wires going to the connector on the ANA board. Remove all the other ANA connectors except for the three ribbon cable connectors. Remove the three standoffs. Remove the other screws that secure the ANA board except for the two in the front. Carefully hinge the board forward revealing the etch side. At the rear of the board, locate OP AMP U68 and associated components. Right next to U68 is a resistor network labeled RN41. The pin of that network closest to the back of the ANA board is pin 1. Look at the etch side (the back side of the board). At the eight pads for this resistor network, you will notice that pins 2 and 3 are connected to a ground trace. Use #30 solid wire to also connect pin 4 and pin 8 of the resistor network to that same ground point, pins 2 and 3. This will decrease the gain of the stage to signals C2F, C4F and C6F. Refer to the attached figure on following page.

REQUIRED MATERIALS: Solder
#30 wire

AUTHOR: Christopher Moore

FIGURE: Install jumper from pin 3 to 4 and to 8.



URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #9

21 June 1982

Page 1 of 6

TITLE: PROGRAM UPDATE, EDITION E4-0 TO EDITION E4-1

UNITS AFFECTED: All 8X32's shipped from the factory after June 21st and/or including Serial Numbers 575 and higher will have Edition 4-1 programs. There will be a sticker on the top cover to indicate this. Earlier units shipped with Edition 4.0 programs will be updated automatically if for some reason they are returned to the factory. Ursa Major requests its dealers to perform this update at no charge on any earlier units that they have in their possession or that they have already turned over to their customers.

REASON FOR CHANGE: Edition 4-1 programs are intended to improve the audio quality. They feature higher echo density, greater diffusion, reduced coloration, better stereo imaging, and reduced left/right channel correlation. We recommend that this change be carried out on all units and doubt that there will be customer preference for Edition 4-0 programs.

SCOPE OF CHANGE: The programs are completely contained in two IC's. The change, therefore, consists of changing two integrated circuits. At the time of updating the IC's, however, we are asking that two resistors on the Analog board be removed. These two resistors couple out of phase reverberation signals, thus increasing left-right correlation. We have had a number of requests to reduce or eliminate the out of phase signal; removing these two resistors does so completely.

REQUIRED MATERIALS:

- #1 Edition 4-0 IC's. Delay PROM Part # 0525-6. Gain PROM Part # 0527-6. Sticker for top cover saying Edition 4-1.
- #2 Tools: #0 Phillips screwdriver. 1/4" nut driver or closest metric equivalent. IC extractor or small delicate screwdriver for removing IC (16 pin DIP & 24 pin DIP). Pair of diagonal cutters.

HOW TO MAKE THE CHANGE:

DANGER: High voltage is present inside unit. Be sure to unplug and remove the line cord completely before beginning disassembly.

WARNING: IC's are susceptible to static electric damage. Keep IC's on conductive foam pad whenever not being used. If possible, work at a grounded work station.

- 1) Unplug the unit. Put it on a padded workbench and remove the top and bottom covers (each cover is secured by 10 small screws).
- 2) Turn the 8X32 upside down on the workbench with the front panel facing you. Refer to Fig. 1 and find the corresponding resistors on the ANA-2 PC board. The left hand resistor (R38) to be removed is color code: red, yellow, orange, gold: 24K. Cut it out with diagonal cutters, being sure that the remaining leads don't short on any nearby circuits. The right hand resistor (R39) to be removed is color code: yellow, purple, orange, gold: 47K. Remove it also. There are no replacement parts for these two resistors; they are completely deleted. This portion of the change eliminates the out-of-phase reverberation.
- 3) Turn the unit right side up, identify CPU-1 daughter board, a 5"x9" PC board sitting up on five metal spacers to the left. Remove the white molex connector and the 16 pin DIP plug going to rear panel "D" connector from the CPU-1. Use the nut driver or other small wrench to remove the five spacers above the board. Check as you do so that the five spacers below the board don't rotate loose as you undo the top spacers.

Change The Delay PROM: Referring to Fig. 2, identify the Delay PROM, the one toward the rear of the chassis in socket position U10. This will either be designated as X116-5, 116-5, 0525-5 or may possibly have no identifying sticker at all. Note the pin 1 end of the IC (toward the rear of the chassis). The new IC must go in just this way. Remove this IC with an IC extractor, or if one is not available, gently pry up each end a little bit at a time using a very small screwdriver. Be very, very certain that when the IC is removed none of the pins have become bent or damaged. Then place the IC in the conductive plastic foam. Next, lift the PROM provided with this kit, Part #0525-6 and check it to be sure that the pins are parallel and straight in both axes. Carefully position the IC with the pin 1 end toward the rear of the unit, the same end where the pin 1 end of the original IC

was located. Refer to Fig. 3 to clarify which end of the IC is pin 1 if you are in doubt. On some IC's, there may be no notch at the pin 1 end, but a small circle, diamond, square or other identifying dot near pin 1. If you put the IC in backwards it will be destroyed. Carefully mesh the pins of the IC in the 20 holes of the socket, jiggling, squirming, looking very carefully to be sure that they are lined up and then press down, gently at first, a little bit more firmly, if necessary, to seat the IC in the socket. Inspect carefully (if possible with a small mirror) to see if any of the pins have been bent under the body or out to one side. All 20 pins, needless to say, have to be in the socket for the circuit to work.

Change the Gain PROM: Refer to Fig. 2 again to identify the second PROM for replacement. This will be labeled 0527-4 or possibly X124-4. It is in IC socket position U85. As before, use an IC extractor or screwdriver to carefully remove the IC. Replace it, again, carefully referring to Fig. 3 for orientation. Carefully check that all the pins have gone into the socket, that none have bent under the body or splayed out to the side.

Special Notes: The Gain and Delay PROMS are paired for proper operation within each program. You cannot mix an Edition 4-0 PROM with an Edition 4-1 PROM in the same machine and have it operate.


Another note: We are calling the first set of Programs shipped Edition 4-0. This second edition that you are installing is Edition 4-1. The first digit indicates the number of programs that are available to the user in the PROM's. Both of these Editions contain four programs. The second digit indicates the revision number of the programs in the PROM's.


4) REASSEMBLY: Place the CPU-1 back on its five spacers and secure it with five spacers. Carefully plug the white molex connector in at the right rear, being sure that it is lined up properly. If it is offset one pin wrong in either direction, you can damage the CPU board. In a similar fashion, be careful when re-installing the DIP plug at the rear of the CPU-1.


When replacing the bottom cover, be careful that the DIP-DIP ribbon cable is folded neatly in a right angle toward the rear as it was when the cover was removed. Re-install the covers, connect the power cord and turn the unit on. It is possible, but unlikely, that this work may have disturbed the user registers. If so, the displays will show all "E"s and register "00".

AUTHOR: Christopher Moore

Figure 1 ANALOG BOARD DETAIL: RESISTOR LOCATION
Remove these two resistors







****You must re-install with pin 1 correct, or you will destroy the IC!****

URSA MAJOR, Inc.

Box 18, Belmont, MA 02178 • Telephone (617) 489-0303
Telex: 921405 URSAMAJOR BELM



8X32 FIELD SERVICE BULLETIN #10

Page 1 of 9
23 July 1983

TITLE: LOWERING THE NOISE LEVEL

UNITS AFFECTED: All units should have the benefit of this update. The factory will switch over to shipping units with this update in August, 1983 (about serial number 700-3). Earlier units will be updated automatically at the factory if they are returned for any other reason; additionally, we will update units returned to us specifically for this change. URSA MAJOR requests its dealers to perform this update at no charge on any units that they have in stock, or that have already been turned over to their customers.

REASON FOR CHANGE: Some 8X32 users have said that they'd like the noise floor to be lower. The idle noise of the 8X32 under some conditions of temperature, drift, etc. can assume a reedy, comb-filter like character which can be annoying, especially in mixes with high levels of reverb and overall system monitor gain. Some users would prefer a higher output signal level: these changes raise it by 6dB.

SCOPE OF CHANGE: The changes should take about 30 to 60 minutes to perform. The two covers must be removed, 3 IC's changed, 4 resistors changed, and 3 capacitors added. The changes accomplish a number of improvements:

1. Improved signal to noise ratio in all-pass circuit, reducing reedy idle channel noise.
2. Improved mid & high-frequency noise level in the presence of signal (due to the addition of modest pre & deemphasis around the reverberant decay circuits).
3. Improved idle channel noise due to changes in the idle gain states chosen by the CPU in conjunction with the Gain PROM.
4. Higher output signal level by 6dB. (Has no net effect on signal to noise ratio of the 8X32, but may help if the 8X32 is connected to a console with marginal input signal to noise ratio or voltage gain on its Echo Receive input).

IMPORTANT! PLEASE RETURN 3 OLD PROM'S TO URSA MAJOR!!

DETERMINING IF THESE CHANGES HAVE YET TO BE DONE TO YOUR UNIT:
Place the unit right side up, with front panel toward your stomach. Locate the CPU board (on standoffs) partially visible through the slots, and covering the left third of the larger motherboard below it. Now angle your vision to peer through the slots near the front right edge of the CPU board to locate a large (24 pin) IC down on the motherboard. This is the Gain PROM, and should have a sticker on it reading 0527-6, 0527-7, or someday maybe even -8 or higher. If the revision number (eg., "-7") is "-7" or higher, your unit has these changes. If not, then you should proceed further.

DETERMINING WHICH KIT YOUR UNIT NEEDS:

There are two kits, differing only in the type of CPU Program PROM's provided. Earlier 8X32's have the Rev-1 CPU using Programs stored in two 2716 PROM's, while the later Rev-2 CPU uses two 2732 PROM's. You can tell which you have in several ways:

1. If you're using a remote unit with your 8X32, you have Rev-2.
2. With the power on, enter Register Number "87" in the Register Display. Now simultaneously depress the two buttons Early Reflection -ms and Decay Time +sec. If all the panel LED's go out except for the Register Number, then you have a Rev-2 CPU. Furthermore, if the displayed number now in the Register Number display is "04", your unit has not yet had these changes. If it's "05" or higher, it has been updated already.
3. Peer through the top cover at the CPU Board. If it has two small screwdriver adjustments sealed with green paint at the right rear, it is a Rev-2 CPU.

If your 8X32 has a Rev-1 CPU, order kit 0744; if Rev-2, order kit 0745.

REQUIRED MATERIALS:

1. Tools: soldering iron with small tip suitable for PC work.
diagonal cutters with small nose
needle-nose pliers and/or tweezers
solder
Philips size #1 screwdriver
IC extractor for 24pin IC's

2. Kit of all parts, complete, for Rev-1 CPU units: 0744.
Kit of all parts, complete, for Rev-2 CPU units: 0745.

CPU PROM'S- "Low" for U7: Rev-1: 0633-5
"Low" for U7: Rev-2: 0742-5
"High" for U8: Rev-1: 0634-5
"High" for U8: Rev-2: 0743-5

Gain PROM: 0527-7.

Resistors: to replace jumper at R98: 4.99k, 1%
to replace resistor R68: 3.09k, 1%
to replace resistor R9: 10.0k, 1%
to replace resistor R10: 10.0k, 1%

Capacitors: mylar capacitor, C300: .018uF, 5%
mylar capacitor, C301: .0039uF, 5%
mylar capacitor, C302: .0039uF, 5%

Note: Capacitors supplied are marked 10%, but sorted at factory to 5%.

Label: "FSB #10 INSTALLED"

DANGER: High voltage is present inside unit. Be sure to unplug and remove the line cord completely before beginning disassembly.

WARNING: IC's are susceptible to static electric damage. Keep IC's on conductive foam pad whenever not being used. If possible, work at a grounded work station. Before picking up or touching an IC, touch first some large nearby metal surface (work bench, BX32 chassis, etc.) to discharge any static charge you may have built up upon your body.

ANOTHER WARNING: Changing PROM's on the CPU involves a slight risk of disturbing the User Register contents, including the chance that all the memories will be lost and erased (in the case of Rev-1 CPU's especially). Therefore, we urge you to note down on paper any register contents that are especially important to you and/or difficult to replace.

HOW TO MAKE THE CHANGES:

1. Unplug the unit. Put it on a padded workbench and remove the top and bottom covers (each cover is secured by 10 screws).
2. Place the BX32 right side up, panel toward your stomach. Locate the CPU board up on its standoffs, and the two 24 pin PROM's plugged into U7 & U8 sockets. Verify that you have the correct IC's to update your CPU (see earlier comments in this bulletin).

Use Fig.1 to locate the 3 PROM's to be changed. Note the pin 1 end of U7: the replacement IC must go in exactly this way. Using the IC extractor, or a small screwdriver, gently remove the IC and set it aside on the foam pad. Next, lift the PROM 0633-5 (or 0742-5) provided with this kit from the foam pad and check it to be sure that the pins are parallel and straight in both axes. Carefully position the IC with the pin 1 end toward the left, the same end where the pin 1 of the original IC was placed. Refer to Fig.2 to clarify which end of the IC is pin 1 if you are in doubt. On some IC's, there may be no notch at the pin 1 end, but a small dot, circle, diamond or other symbol. If you put the IC in backwards it will be destroyed! Carefully mesh the pins of the IC in the 24 holes of the socket, jiggling, squirming, looking very carefully to be sure that they are lined up and then press down, gently at first, a little bit more firmly if necessary, to seat the IC all the way in the socket. Inspect carefully (if possible with a small mirror) to see if any of the pins have been bent under the body or out to one side.

Now repeat the last paragraph's procedure with U8, the other FROM on the CPU, using the new PROM 0634-5 (or 0743-5) to replace the old one.

Finally, locate the Gain PROM (see Fig.1) on the motherboard right near the right edge of the CPU board, and replace it with the new PROM, part number 0527-7.

You are now through with the IC replacements and with work on the top side of the 8X32.

3. Now turn the 8X32 upside down, with the panel toward your stomach, and refer to Fig.3 to get oriented as to where you will be making the changes on the ANA board.

4. CHANGING A RESISTOR: We recommend the following procedure to replace a resistor (or the jumper at R98):

Cut and bend the resistor leads according to Fig.4.

Use the iron and solder to tack a tiny solder blob onto the ends of the resistor leads.

Find the old resistor or jumper to be replaced. Use the iron and solder to tack a small solder blob on its leads where they enter the PC board.

Now tack solder the new resistor across the old, soldering at the points where the old resistor leads enter the PC board. Refer to Fig.5.

Use the diagonal cutters to carefully cut away the old resistor, by cutting its leads near its body. Remove and discard the remains of the old resistor.

5. Following the procedure of (4) above, change the following resistors:

	Component #	Old Value	New Value
i)	R68	2K, 5% (red,black,red, gold)	3.09K, 1% (orange,blk,white,brown)
ii)	R98	jumper (white)	4.99K, 1% (yel,white, white,brown)
iii)	R9,R10	5.1K,5% (green,brown,red, gold)	10.0K, 1% (brown,blk,blk,red)

Fig.3 will help you locate them.

6. Referring again to Fig. 4, prepare the 3 capacitors provided by cutting the leads and soldering small solder blobs on the lead ends as you did with the resistors.

7. Find the 3 resistors across which these 3 capacitors are to be tack soldered and prepare these resistors with small solder blobs.

8. Now add the 3 capacitors as follows (Refer to Fig.6):

- i) C300 .018uF, 5%: tack solder across R98 (just installed).
- ii) C301 .0039uF,5%: tack solder across R41
- C302 .0039uF,5%: tack solder across R42
(R41 and R42 are 12K,5%: brown,red,orange, gold)

9. Please make a last check:

Are all the solder joints sturdy? You should be able to push gently on each newly installed component and have it remain firmly soldered.

Look carefully where you soldered for blobs, shorts, etc.

Be sure all removed components are set aside on the foam pad and that none remain in the unit.

Be sure you have carried out each step and that you have no leftover new components in the kit.

Double-check your IC insertions for correct pin 1 orientation, correct IC's in each socket, no bent pins, etc.

10. Apply the supplied sticker "FSB #10 INSTALLED" to the chassis rear panel.

REASSEMBLY: Replace the top cover with its 10 screws. It is sometimes helpful to not tighten the screws fully until all have been started and are engaged in the mating cover threads.

When replacing the bottom cover, be careful that the DIP-DIP ribbon cable is folded neatly in a right angle toward the rear as it was when the cover was removed.

When both covers are installed, connect the power cord and turn the unit on. It is possible that changing the CPU PROM's may have disturbed the user register, but this is unlikely. If they were disturbed, CPU Rev-1's will show a display of all "E"'s and Register "00". Rev-2 CPU's will show a display of panel settings with ".bd." flashing in the Register Display. In the case of Rev-1 CPU's, all user contents will have been lost, while in Rev-2 CPU's, the ".bd." indicates that some error in memory was found upon power-up, but the contents will not have been erased. Much or most of the user register contents may still be valid, but you should check carefully.

QUICK LISTENING VERIFICATION: After making these changes, it's a good idea to check for normal operation before returning to the customer.

- i) Connect input and output leads and a signal source so you can listen to the 8X32.
- ii) Set the panel to Early Reflections, Level 8; Initial Reverb, Level 1; and Decay Time, 0.0. You should hear equal loudness levels in the L&R outputs.
- iii) Set the panel to Early Reflections & Initial Reverb, Level 1; Program to Plate II; Decay Time to 3.0 sec. You should hear equal loudness reverb in both outputs, with the same balanced frequency response as before the changes.

IMPORTANT: Please return the 3 original PROM's to:

URSA MAJOR, Inc.
Box 18; 50 Trapelo Rd.
Belmont MA 02178 USA.

AUTHOR: Christopher Moore




Fig.2 PROM Orientation Notch, dot, diamond, or other mark at this end.

*** You must re-install with pin 1 correct, or you will destroy the IC!




Fig.1 Location of 3 PROM's




Fig.3 ANA Board: locations of changed R's and C's



Fig.4 Resistor and Capacitor Soldered in at R98 position




Fig.5 Resistor Tack-Soldered in place at R68 position.



Fig.6 Capacitors Tack-soldered in place across R41 & R42.

APPENDIX B. PARTS LISTS

The following are the parts lists for the circuit modules, the chassis, and the remote control of the 8X32. They are intended to help you should you ever have to replace a part or order one from the factory.

8X52 MOM-2 ASSEMBLY 1

<u>STOCK#</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>RESISTOR 5% 1/4w CF</u>			
202-0105	100 Ω	R3	1
202-0106	150 Ω	R28	1
202-0462	270 Ω	R26	1
202-0109	510 Ω	R13,R20	2
202-0110	1.0K	R1,R2	2
202-0111	1.1K	R18,R19	2
202-0112	2.0K	R25	1
202-0113	2.4K	R21,R22	2
202-0115	4.7K	R6,R7,R8,R9	4
<u>RESISTOR 1% 1/4w MF</u>			
203-0470	124 Ω	R10,R14,R17, R24,R27,R31	6
203-0474	619 Ω	R15,R16	2
203-0473	383 Ω	R11	1
203-0475	1.07K	R23	1
203-0477	1.37K	R29,R30	2
203-0480	3.48K	R12	1
<u>RESISTOR NETWORK (SIPS)</u>			
207-0501	10pin 2.2K	RN1	1
206-0502	8pin, 2.2K	RN8	1
207-0500	10pin, 3.3K	RN9,RN10,RN11	3
<u>DIODES</u>			
300-0155	1N4004	D3,D4,D5,D7-16, D18-D25	21
300-0377	MR751	D1,D2	2
300-0158	1N4735A	D6	1
300-0157	1N5231B	D17	1
320-0187	SCR122F	SCR	1
341-0439	FET	Q1	1
380-0444	10MHz Crystal	XTAL	1
370-0190	Ferrite Bead	FB1,FB2,FB3	3
<u>SOCKETS</u>			
520-0148	8pin,Dip		2
520-0149	14pin,Dip		26
520-0150	16pin,Dip		48
520-0152	20pin,Dip		14
520-0153	24pin,Dip		1
522-0052	TO220	U93-U97	5
<u>CAP, TANTALUM DIPPED</u>			
241-0127	4.7uF/25V	C2,C6,C10,C12 C15,C18,C20	7
<u>CAP, ALUMINUM ELECTROLYTIC</u>			
240-0452	22uF/35V	C9,C14,C17, C22,C95,C98	6
240-0260	330uF/16V	C96,C97	2
240-0356	2200uF/35V	C23-C26	4
240-0357	15000uF/16V	C4,C5	2
<u>CAP MICA</u>			
242-0137	24PF	C1 (C4 at XTAL)	1
<u>CAP CERAMIC DISC</u>			
245-0131	.005uF/1600V	C27,C28	2
245-0133	.02uF/50-100V	C29,C31-38,C40-C48 C51-C78,C93,C94	48
245-0294	.1uF/50V	C8,C30,C39,C49 C50,C79-C92	19
670-0191	Jumper, .5inch	RN7 Jumper 9	11
<u>MOM-2 PCB</u>			
600-0192	Fuse Clip		6
453-0045	Voltage Select Switch	S1	1
640-0218	Screw 4-40 x 5/16 PPB		1
643-0222	Nut, KEP #4		1

8X32 MOM-2 ASSEMBLY 2

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>IC's DIGITAL</u>			
330-0161	74LS00	U14,U45	2
330-0162	74LS04	U3,U4,U11,U29,U37,U67 U69,U76,U77,U19,U88	11
330-0164	74LS08	U2,U23,U40,U43,U66,U87	6
330-0210	74LS10	U32	1
330-0488	74LS11	U7,U30	2
330-0166	74LS30	U39	1
330-0167	74LS74	U1	1
330-0315	74LS85	U33,U47,U65,U83	4
330-0270	74LS86	U31	1
330-0169	74LS163	U16,U17	2
330-0334	74LS175	U5,U6,U36,U50,U82,U84	6
330-0212	74LS189	U12,U71	2
330-0215	74LS253	U68	1
330-0171	74LS257	U9,U13	2
330-0216	74LS283	U21,U34,U35,U46,U48,U49	6
330-0316	74LS373	U89-U92	4
330-0317	74LS374	U24,U25,U28,U73,U74,U75 U78,U79,U80,U81,U86	11
330-0173	74LS393	U18	1
330-0324	74LS670	U72	1

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>PROMS</u>			
350-0521	82S123 (0521-4)	U20	1
350-0522	82S123 (0522-3)	U22	1
350-0523	82S123 (0523-2)	U26	1
350-0524	82S123 (0524-2)	U38	1
350-0520	82S123 (0520-1)	U15	1
350-0525	TBP28L22N (0525-5)	U10	1
350-0526	TBP28L22N (0526-7)	U27	1
350-0527	2716 (0527-4)	U85	1

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>16K RAM</u>			
351-0336	5290N	U51-U64	14

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>SAR</u>			
330-0174	2502	U41,U42	2

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>MISC</u>			
303-0445	Display, Red 7 segment Fl.	U44	1
453-0044	Power Switch	J2	1
510-0425	26pin Header Shroud Conn.	J3	1
510-0426	34pin Header Shroud Conn.	J2	1
520-0151	Socket 16pin EBY	J1	1
630-0430	Standoff 5/8inch long M/F	SOA,OB,OC,OD,OE	5
630-0433	Standoff 1.5inch long F/F	SOF,SOG	2
630-0631	Standoff 13/16in long MF	SOB,SOE,SOG	3
640-0224	Screw 6-32 x 1/4 PPB	SOF,SOA,SOC,SOD	4
644-0288	Washer Internal Star #6	SOA-SOG	7

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>FUSES</u>			
440-0581	8AG, 5.0 A	F3	1
440-0193	3AG, .75 SB	F1,F2	2
440-0195	3AG, .375 SB	F1,F2	2
680-0515	Cable, Ribbon 40pin	J4	1

Hardware Assembly: Always

Top Side of Board

5	5/8 inch long M/F Standoffs	SOA-SOE
2	1.5 inch long F/F Standoffs	SOF,SOG

Bottom Side of Board

3	13/16 inch long M/F Standoffs	SOB,SOE,SOG
4	6-32 x 1/4 PPB Screws	SOA,SOC,SOD,SOF
7	#6 Internal Star Washers	SOA-SOG
1	EBY 16pin Socket	J1, Bottom

8X32 AVA-2 ASSEMBLY 1

STOCK# PART LOCATION QTY

Resistors CF, 1/4W, 5%

202-0103 27 R45,53,55,58 4

202-0105 100 R69,70,80 3

202-0606 330 R99,101 2

202-0463 390 R82 1

202-0109 510 R5 1

202-0112 2.0K R21,34,68,77,78,81,97 7

202-0607 2.7K R94 1

202-0114 3.0K R104 1

202-0464 3.9K R66,67,93 3

202-0608 5.1K R9,10 2

202-0609 11.0K R1 1

202-0119 12.0K R40,41,42 3

202-0610 22.0K R2,6 2

202-0120 24.0K R3,7, 2

202-0611 27.0K R4,8 2

202-0124 240.0K R46,47,54,56,59,100,119 14

202-0639 680.0K R35 1

680-0191 Jumper, .5inch R98,117,131 3

Resistors MF, 1/4W, 1%

203-0469 51.1 R23,36,37,102 4

203-0612 200 R50,57,60,103 4

203-0472 210 R48 1

203-0474 619 R43,44 2

203-0475 806 R71,72 2

203-0083 1.0K R73,74,75,76,79 5

203-0102 1.24K R51,52,61,62 4

203-0478 2.61K R19,32,91 3

203-0479 2.74K R49 1

203-0613 3.09K R13 1

203-0087 4.02K R26 1

203-0090 4.53K R15,122 2

203-0481 4.99K R108 1

203-0615 5.23K R10 1

203-0616 5.49K R120,124 2

203-0617 6.04K R128 1

203-0482 6.65K R15,28,87 3

203-0618 7.68K R106 1

203-0093 10.0K R22,35,63-65,109,111,114,116 9

203-0636 10.7K R23, Unbent 8

203-0637 11.0K R25, Unbent 8

203-0094 11.3K R18,31,90 3

203-0095 12.4K R14,27,86 3

203-0619 17.8K R12 1

203-0483 20.5K R17,30,89 3

203-0632 24.9K R20,33,92,105 4

203-0100 25.5K R11,12,16,24,25,29,83,84,88 9

203-0620 26.1K R13,26,85 3

203-0485 29.4K R95,96,107 3

Res, Net, Dip, Thin Film

210-0635 330n,.05%, 8pin R14A,RN14B,RN15A,RN15B 4

210-0598 2.0K,.05%, 8pin RN16-RN21,RN28,RN29 8

210-0326 10.0K,.05% 8pin RN7-RN10,RN30-RN33 8

210-0327 10.0K,.1% 14pin RN6,RN11,RN12,RN45 4

Res, Net, Dip, Thick Film

205-0147 100n, 2%, 16pin J18 1

205-0417 1.0Kn, 2%, 16pin RN2-RN5 4

205-0600 8.2Kn, 2%, 16pin RN26 1

205-0601 9.1Kn, 2%, 16pin RN24 1

205-0602 10.0K, 2%, 16pin RN22 1

205-0604 12.0K, 2%, 16pin RN27 1

205-0453 22.0K, 2%, 16pin RN1 1

SIPS

206-0144 2.0K, 8pin RN13,34,55,56,59,40,44 7

206-0146 47.0K, 8pin RN37,38,41,42, 4

212-0506 200n, 6pin RN43 1

8X32 ANA-2 ASSEMBLY 1

STOCK #	PART	LOCATION	QTY
201-0442	10K, RECTANGLE, MULTITURN	RV9	1
201-0443	200.0K, Round, SINGLE TURN	RV7, RV8	2
201-0586	200.0K, Rectangular, SINGLE TURN	RV1-RV6, RV10, RV11	8
270-0190	Ferrite Bead	ES, 6, 7, 8, 10	5
300-0154	DIODE, IN4148	CRI-CR16	16
Connector, Header, Right Angle, Locking, .156			
510-0416	3pin	J20, J23	3
510-0672	4pin	J20	1
510-0373	6pin	J8, J19	2
IC's			
315-0199	LF398H Sample & Hold	U29, 31, 35, 37	4
CAPACITORS			
245-0133	Cer, Disc .02uF/50V	C1, 2, 5, 6, 15, 16, 21, 22, 31, 33, 35, 38, 40, 43, 44, 46, 47, 49, 112, 136-143, 152-157, 179, 180, 187, 188, 207, 208, 211, 212	41
245-0182	Cer, Disc .01uF/50V	C101, 121	2
245-0294	Cer, Monolithic .1uF/50V	C83, 84, 87, 88, 89, 91, 93, 94, 96, 98, 100, 102, 103, 106, 107, 108, 110, 113, 116, 117, 119, 120, 122, 124, 167, 172, 207, 208	32
240-0136	Alum, Elec, RAD 4.7uF/35V	C14, 17-20, 30, 32, 135, 197	9
240-0452	Alum, Elec, RAD 22uF/25V	C39, 42, 45, 48, 97, 99, 104, 115, 118, 123, 131, 132, 160-165, 182, 184, 186, 200, 202, 204, 206, 209	26
242-0495	Axial 330uF/16V	C3	1
243-0139	Polypropolyne 120pF	C85, C94	2
243-0140	Polypropolyne 220pF	C196	1
243-0141	Polypropolyne 1000pF	C7-13, C23-29, C50-82, 86, 90, 92, 145-151, 159, 174-178, 185, 189- 195, 198, 173	75
247-0599	Stacked Film .22uF/63V	C125-130	6
241-0128	Tant-Dipped 22uF/16V	C109	1
SOCKETS			
520-0148	8pin	U1, 7, 12, 13, 28, 30, 32, 36, 38, 53, 54, 55, 68, 69, 71, 72, 75, 76, 78	19
520-0149	14pin	U3, 8-11, 14, 15, 16, 18, 19, 21, 22, 24, 25, 27, 62-67, 73, 74, 77	24
520-0150	16 pin	U2, 4, 5, 6, 17, 20, 23, 26, 33, 34, 39, 44, 45, 46, 48, 49, 51, 52, 56-61, 70, 71, 73, 717	27
520-0152	20 Pin	U47, U50	2
520-0151	EBY 16 Pin	J1, J11, J12	3
710-0396		ANA-02 8X32	1

8X32 ANA-2 ASSEMBLY 2

<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>OP-AMP's</u>			
540-0579	TLO72	U1,7,28,53,54,55,68,69,72,76	10
540-0203	TLO74	U3,16,18,19,21,22,24,25,27,62-64	12
540-0207	4741	U8-11,73,74,77	7
540-0337	5532N	U12,13,32,36,71,75,78	7
540-0198	5534N	U30,38	2
<u>COMPARATOR's</u>			
540-0568	OMP-5FZ	U40,41,42,43	4
<u>ANALOG SWITCH</u>			
545-0200	MC14051B	U2,4,5,6,17,20,23,26,39,44	10
545-0201	MC14052B	U33,34,56-61,70	9
<u>DAC</u>			
555-0337	DAC-08HQ	U45,46,51,52,	4
555-0322	AM6012DC or PMI DAC312FR	U47,50	2
<u>LOGIC</u>			
530-0163	7406	U14,15, 65,66,67	5
530-0534	74LS175	U48	1
530-0215	74LS253	U49	1
<u>MISC.</u>			
680-0513	Ribbon Cable,26pin	J2	1
680-0514	Ribbon Cable,34pin	J3	1
670-0498	Dip shunt,16pin	J13	1
205-0147	Res,Net,Dip,16pin, 2%, 100n	J17	1

8X32 CPU-01 Rev 2 ASSEMBLY 1

<u>STOCK#</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>Resistor, 1/4w, 5%, CF</u>			
202-0606	330n	R8	1
202-0110	1.0kn	R7,R16	2
202-0720	2.2kn	R13	1
202-0114	3.0kn	R14	1
202-0721	3.3kn	R9	1
202-0464	3.9kn	R11,R20	2
202-0117	8.2kn	R10,R12	2
202-0572	33.0kn	R5,R18	2
202-0727	110.0kn	R17	1
202-0124	240.0kn	R4	1
202-0569	1.0Mn	R1,R2,R15	3
202-0722	2.2Mn	R19	1
202-0728	3.0Mn	R6	1
<u>Resistor, Network, 2%, 10 PIN, SIP</u>			
207-0504	1.0Mn	RN1	1
<u>Resistor, Variable, PC Mount</u>			
201-0729	Cermet, Single Turn, Round, 10Kn	RV1,RV2	2
<u>Ferrite Beads</u>			
270-0190		FB1,FB2	2
<u>Crystal</u>			
280-0715	1.8432 MHz	XTAL	1
<u>Diodes</u>			
300-0154	1N4148	D1,D2,D4	3
<u>Diode Schottky</u>			
304-0725	1NG263	D3	1
<u>Transistors</u>			
342-0717	2N3904	Q2,Q3,Q5	3
342-0718	2N3906	Q4	1
<u>Cap, Alum Elec, Axial</u>			
242-0259	0.47uf/50v	C1	1
242-0495	330uf/16v	C10	1
<u>Cap, Tant, Dipped</u>			
241-0128	22uf/16v	C9,C11	2
<u>Cap, Ceramic, Monolithic</u>			
245-0294	.1uf/50v	C2,3,13,C15-21	10
<u>Cap, Ceramic Disc</u>			
245-0726	56pf	C7	1
245-0130	100pf	C5,C8	2
<u>Sockets, EBY</u>			
521-0151	16 PIN	J10	1
521-0440	24PIN		1
<u>Socket, Dip, Solder Tail</u>			
521-0148	8 PIN		3
520-0149	14 PIN		8
520-0150	16 PIN		4
520-0459	18 PIN		2
520-0152	20 PIN		6
520-0153	24 PIN		2
520-0460	40 PIN		3
<u>Headers, Male, Right Angle</u>			
510-0373	6 PIN, .156" spacing	J6	1
510-0427	40 PIN, .1 Grid Shroud	J4	1

8X32 CPU-01 Rev 2 ASSEMBLY 1

PCB

710-0406 8X32, CPU-01, Rev 2 1

ASSEMBLY NOTES

Mask: Battery, SOA-SOE, J9
Glue under XTAL
Solder J6

CPU-01 Rev 2 OPTION "FOR NON-REMOTE UNITS"

Remove U19 (WD2123 UART)
U27 (74LS02)
U18 (74LS244)

Substitute into U19 a Header jumpered together PIN 8, 13, 10 and 7.

8X32 CPU-01 Rev 2 ASSEMBLY 2

<u>STOCK#</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>IC, LOGIC</u>			
330-0161	74LS00	U1,9,16	3
330-0209	74LS02	U27*	1
330-0167	74LS74	U21,25	2
330-0332	74LS138	U13,15,17,24	4
330-0170	74LS244	U11,12,18*	3
330-0316	74LS373	U4	1
330-0317	74LS374	U10,14	2
<u>IC, PROMS, MEMORY</u>			
350-0724	2732 programmed to:		2
352-0633	PROGRAM #633/U7		1
352-0634	PROGRAM #634/U8		1
<u>IC, RAMS, MEMORY, STATIC</u>			
330-0494	UPD444/65144	U5,U6	2
<u>IC, VOLTAGE REGULATOR</u>			
340-0716	ICL8212CPA	U2,U28	2
<u>IC, INTERFACE</u>			
342-0381	1488	U23	1
342-0382	1489	U22	1
<u>MISC</u>			
340-0383	Timer NE555	U26	1
330-0386	IC, Keyboard/Display Interface 82792	U20	1
330-0380	IC,uP, 8085A	U3	1
330-0709	IC, Dualuart, WD2123P or A	U19*	1
900-0496	Battery, Lithium, 3.0v, 1Ah	BAT	1
510-0731	Header, 14PH, DIP		

ASSEMBLY NOTES:

Header to be programmed and returned not mounted.

* may be removed and returned to stock.

BATTERY DANGEROUS, WILL EXPLODE IF REVERSED, GROUNDED, SHORTED, OR TOUCHES OTHER BATTERIES.

PAN-1 ASSEMBLY 1

<u>STOCK#</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>SWITCHES</u>			
450-0330	Black push button legend +	N2,4,6,8,10	5
450-0330	Black push button legend -	N1,3,5,7,9,	5
450-0331	Black push button with LED saddle	N11-N26	16
Black push button Legend:			
450-0329-0	0	N27	1
450-0329-1	1	N28	1
450-0329-2	2	N29	1
450-0329-3	3	N30	1
450-0329-4	4	N31	1
450-0329-5	5	N32	1
450-0329-6	6	N33	1
450-0329-7	7	N34	1
450-0329-8	8	N35	1
450-0329-9	9	N36	1
<u>IC's</u>			
340-0354	ULN-2803A	U1	1
330-0332	74LS138	U2	1
330-0387	4514	U3	1
340-0356	UDN-2981A	U4,U5	2
<u>CAPACITORS</u>			
241-0128	22uF/25V TANT	C1	1
245-0294	.1/50V CERAMIC	C2	1
242-0495	330uF/16V Alum. Elec. Axial	C3	1
<u>CONNECTORS</u>			
510-0046	3pin Male Header	J1	1
680-0512	24pin Cable Dip to Dip	J2	1
<u>RESISTORS</u>			
204-0581	75 $\frac{1}{2}$ w 5% Res	R9,R10	2
204-0582	100 $\frac{1}{2}$ w 5% Res	R1-8,R11-15	13
<u>STOCK #</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>LEDs</u>			
270-0190	Ferrite Bead	FB1	1
302-0352	Red T.I. Package	D28-D42,D15	15
302-0353	Green T.I. Package	D43	1
302-0345	Red Top Hat	D1,D8	2
302-0347	Yellow Top Hat	D2,D9	2
302-0346	Green Top Hat	D3-D7,D10-D14	10
<u>7 SEGMENT DISPLAYS</u>			
303-0349	Red Left Hand Decimal Point	D17,D20,D23	3
303-0348	Red Right Hand Decimal Point	D18,D19,D21, D22,D24,D25	6
303-0350	Green Right Hand Decimal Point	D27	1
303-0351	Green Left Hand Decimal Point	D26	1
710-0415	PAN-1 PCB		1
915-0564	MASK,8X32		1
915-0659	MASK, 8X32 Remote		1

8X32 FRONT PANEL ASSEMBLY WITH PAN-1

<u>STOCK #</u>	<u>PART</u>	<u>QUANTITY</u>
702-0283	Front Panel	1
640-0446	Screw 4-40 x 4/16 PP	6
644-0223	#4 Internal Star Washers	6
701-0238	Bracket Keystone #617	4
640-0449	Screw, Socket Flat Head 6-32 x 5/16	4
643-0227	Kep Nut #6	4
715-0340	Window Large	1
715-0341	Window Small	1

8X32 REM-01 REV 1 ASSEMBLY 1

<u>STOCK:</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
202-0118	Res, CF, 1/2w, 5% 10.0Kn	R1	1
300-0154	Diode, 1N4148	D1, D2	2
270-0190	Ferrite Bead	FB1	1
280-0692	Crystal, 2.4576 MHz	X1	1
<u>CAPACITOR</u>			
Aluminum, Electrolytic, Axial			
242-0694	.47uf/50v	C2	1
242-0690	47uf/25v	C6, C7, C10	3
242-0495	330uf/16v	C1, C8, C9	3
245-0294	Tantalum, Dipped 22uf/16v	C15	1
241-0128	Monolithic, Ceramic .1uf/50v	C3, C11, C12, C13 C14	5
510-0427	40Pin, Male Header, Right Angle Shroud	J1	1
<u>Socket, Solder Tail, Dip</u>			
520-0148	8 Pin		2
520-0149	14 Pin		7
520-0150	16 Pin		7
520-0459	18 Pin		3
520-0153	24 Pin		1
520-0460	40 Pin		2
640-0218	4-40x5/16 PPB Screw		1
643-0688	4-40 ESNA Nut		1
620-0701	Terminal Ring, #4		2
680-0552	Wire, 2.0 inch, 20 AWG		2
710-0661	PCB, REM-01		1
740-0682	LM2930T-5.0 REG	U22	1

8X32 REM-02 REV 0 ASSEMBLY 2

<u>STOCK:</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
<u>IC, INTERFACE</u>			
340-0381	1488	U19	1
340-0382	1489	U20	1
<u>IC, CMOS, LOGIC</u>			
330-0675	4011	U8, U11	2
330-0681	4015	U9	1
330-0676	4023	U4	1
330-0677	4040	U3, U21	2
330-0678	174	U7	1
330-0679	4556	U17	1
330-0689	4081	U6	1
330-0633	4584	U13	1
<u>MISC, IC</u>			
330-0384	4712	U14	1
330-0385	6402	U1	1
330-0386	8279	U2	1
330-0387	4514	U10	1
<u>IC, DRIVERS</u>			
340-0356	UDN-2981A	U15, U16	2
340-0354	ULN-2803	U18	1
<u>IC, REGULATORS</u>			
340-0683	ICL-7660-CPA	U5, U12	2
680-0708	Dip to D Cable-30"	J2	1

8X32 PAN-02 ASSEMBLY

<u>STOCK:</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
450-0330(+)	Black Push Button Legend (+)	N2,4,6,8,10	5
450-0330(-)	Black Push Button Legend (-)	N1,3,5,7,9	5
450-0331	Black Push Button With Saddle	N11-N26	16
450-0329-0	Black Push Button Legend 0 N27		1
450-0329-1	Black Push Button Legend 1 N28		1
450-0329-2	Black Push Button Legend 2 N29		1
450-0329-3	Black Push Button Legend 3 N30		1
450-0329-4	Black Push Button Legend 4 N31		1
450-0329-5	Black Push Button Legend 5 N32		1
450-0329-6	Black Push Button Legend 6 N33		1
450-0329-7	Black Push Button Legend 7 N34		1
450-0329-8	Black Push Button Legend 8 N35		1
450-0329-9	Black Push Button Legend 9 N36		1

RESISTORS

204-0682	100n, $\frac{1}{2}$ w, 5/8, CF	R1-R10	10
----------	--------------------------------	--------	----

LEDS

302-0349	RED, T1 PACKAGE	D1,D8,D15,D28-D42	17
302-0691	YELLOW, T1 PACKAGE	D2,D9	2
302-0353	GREEN, T1 PACKAGE	D3-D7, D10-D14,D43	11

DISPLAYS, SEVEN SEGMENT, .3 inch common an

303-0349	RED, Left Decimal	D17,D20,D23	3
303-0348	RED, Right Decimal	D18,D19,D21,D22	6
		D24,D25	
303-0350	GREEN, Right Decimal	D27	1
303-0351	GREEN, Left Decimal	D28	1
710-0656	PAN 02		1
915-0659	MASK 8X32 REMOTE		1
690-0707	Ribbon Cable, 40 Pin, Transition to Shroud		1

REMOTE ASSEMBLY 8X32

<u>STOCK</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
715-0641	Window, Remote 8X32 Small, Red		1
715-0647	Window, Remote 8X32 Large, Grey		1
702-0655	8X32 Remote, Bottom Cover		1
702-0697	8X32 Remote, Top Cover		1
702-0643	8X32 Remote, Side Piece		2
541-0696	Foot, Adhesive Rubber .5 inch rec		4
640-0217	4-40 x 3/16 PPB		2
640-0218	4-40 x 5/16 PPB		7
640-0660	6-32 x 5.483 inch		2
640-0593	Jacksocket Assembly		1
644-0223	#4 Internal Starwasher		4
630-0634	Spacer, Hex, .250inch, 4-4U, M/F		5
630-0635	Spacer, Hex, .375inch, 4-4U, M/F		5
690-0695	12 inch, Plastic Tubing, OP .250, ID .160		
915-0659	Mask, 8X32 Remote		1
720-0265	1 inch, Foam Tape, Adhesive $\frac{1}{4}$ " x 1/8"		
730-0705	Box, 8X32 Remote, Inner Carton		1
730-0704	Box, 8X32 Remote, Outer Carton		1
730-0706	Set, Foam Pad, 8X32 Remote		1

Cable Assembly, 8X32 Remote

8X32 REMOTE CABLE ASSEMBLY

<u>STOCK</u>	<u>PART</u>	<u>LOCATION</u>	<u>QTY</u>
490-0710	AMP205206-1 Male Plug "D" 15 Pin		1
510-0711	AMP205205-1 Female Plug "D" 15 Pin		1
525-0712	Pin, Male Terminal		5
525-0713	Pin, Female Terminal		5
500-0714	Hood		2
640-0593	Screw Lock Assembly (Pair)		1
640-0594	Screw with Clip (Pair)		2
670-0733	Cable, 4 conductor with Drain and Shield		

PIN OUT FOR MALE & FEMALE PLUG OF CABLE ASSEMBLY

Pin #1	Shield	Drain
Pin #3	White	Data from Remote to 8X32
Pin #8	Black	Ground
Pin #11	Green	Data to Remote from 8X32
Pin #15	Red	Raw Vcc

D to DIP PIN OUT

<u>D Pin</u>	<u>Dip Pin</u>
15	15
8	1
11	11
3	8
1	8

CHASSIS ASSEMBLY 8X32 PARTS LIST

MISC.

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
704-0370	Heat Sink, TO3 Style	1
640-0372	Cover, TO3	1
640-0558	Screw Cover	2
630-0423	Insulator, TO3	1
630-0282	Insulator, TO-220	5

Bell Housing
4 Fibre Washers

IC's

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
340-0435	Voltage Regulator LM317T	3
340-0436	Voltage Regulator LM337T	2
340-0437	Voltage Regulator LM388K	

Located:U93,U95,U96
Located:U94,U97

MISC.

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
605-0444	Bushing, .50 inch	1
605-0445	Bushing, .750 inch	1
702-0422	Bracket, 8X32	1
702-0418	Chassis, 8X32	1
470-0309	Transformer, 8X32	1
702-0509	Plug Cover, 8X32	1
680-0516	Cable, Dip to "D" Female connector with hardware	1

SCREWS

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
640-0218	4-40 x 5/16, Black, Phillip, Panhead	7
640-0219	4-40 x 5/16, Black, Phillip, Flat 82	8
640-0224	6-32 x 4/16, Black, Phillip, Panhead	14
640-0560	6-32 x 12/16, Black, Phillip, Panhead	2
640-0447	6-32 x 6/16, Hex cap, Black	4
640-0561	8-32 x 4/16 Sheet metal, Black, Phillip Panhead	2
640-0562	8-32 x 1 12/16 Hex head, Black Screw	4

CHASSIS ASSEMBLY 8X32 PARTS LIST con't

NUTS

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
643-0688	#4 ESNA nut	5
643-0222	#4 Kep nut	2
643-0227	#6 Kep nut	4
643-0450	#6 ESNA nut	2
643-0561	#8 ESNA nut	4

WASHERS

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
644-0234	#4 Nylon shoulder washer	5
644-0228	#6 Internal star washer	13
644-0559	#6 Lock washer	2

MISC.

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
701-0281	Bracket #614 Keystone	2
530-0272	Tie wrap	15

701-0281 Bracket #614 Keystone to be sent to L & M Sheet Metal

640-0593 Set, Jacksocket Assembly, 4-40 Hardware for "D" connector to chassis/

CHASSIS ASSEMBLY CONNECTOR PARTS LIST

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
490-0257	AC Power Receptacle	1
523-0371	Socket TO3	1
490-0243	XLR-3 Male Bulkhead Mount	2
490-0247	XLR-3 Female Bulkhead Mount	2
490-0451	XLR-AN3 Male Cable	1
490-0264	Female, 3 pin, .156 Spacing, Locking	5
490-0539	Female, 6 pin, .156 Spacing, Locking	2
200-0388	Pot, 10K, Bulkhead Mount with two nuts and a washer	1
490-0673	Female, 4 pin, .156 Locking	1
525-0057	Pin, Crimp, 22 AWG-26 AWG	28
525-0376	Pin, Crimp, 18 AWG-24 AWG	2
525-0300	Pin, Crimp, Power Receptacle	3
620-0239	Solder Lug, Ring Terminal	2
670-0671	Wire, 43.0 inch, Shield, 3 conductor, UL1015, Cut and Strip	
670-0275	Wire, 6.0 inch, Shielded, 2 conductor UL1015, Tinned, Cut and Stripped .250 inch	
680-0549	Black, 9.0 inch, 20 AWG	
680-0550	Blue, 11.0 inch, 20 AWG	
680-0552	Black, 2.0 inch, 20 AWG	
680-0555	Black, 3.0 inch, 20 AWG	
680-0554	Red, 3.0 inch, 20 AWG	
680-0551	Red, 2.0 inch, 20 AWG	
680-0556	Green, 3.0 inch, 20 AWG	
680-0553	Green, 2.0 inch, 20 AWG	
680-0546	White, 15.5 inch, 20 AWG	
680-0547	Black, 16.0 inch, 20 AWG	
680-0548	Green, 3.50 inch, 20 AWG	
680-0564	Green, 16 inch, 20 AWG	
680-0557	Purple, 11.5 inch, 16 AWG	
680-0558	Red, 11.5 inch, 16 AWG	
680-0563	Bare wire, 20 AWG	
680-0273	6 inch, Shrink tubing, .250 inch, 20 AWG	

8X32 POST BURNIN ASSEMBLY NOTES

ANA

STANDOFF

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
650-0432	Standoff, 3/4, Female/Male	3
640-0224	Screw, 6-32 x 1/4, Phillip, Panhead, Black	7
644-0228	Washer, Internal star #6	7

CPU

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
650-0429	Standoff, 13/16, Female/Female, Hex 6-32	5

8X32 POST BURNIN AND SHIPPING

<u>STOCK #</u>	<u>PART</u>	<u>QTY</u>
640-0687	6-32 x 2/16 Screw, Panhead, Black, Phillip	
640-0224	6-32 x 4/16 Screw, Panhead, Black, Phillip	2
640-0217	4-40 x 3/16 Screw, Panhead, Black, Phillip	22
644-0288	#6 Internal star washer	20
530-0268	Cable clamp, EBY 16 pin socket	5
550-0441	Cable clamp, EBY 24 pin socket	1
680-0511	Cable, Ribbon DIP-DIP, 16 pin, 9.0 inch	2
550-0428	Button, Power, 8X32	1
702-0420	Cover, Top, 8X32	1
702-0421	Cover, Bottom, 8X32	1
541-0253	Rubber foot, Adhesive backed	4
680-0266	Power cord	1
750-0566	Shipping carton, 8X32	1
730-0542	Bag, Plastic 8X32	1
730-0567	Foam End cap, 8X32	2
730-0702	Outer shipping carton, 8X32	1
730-0703	Shock absorbers, 8X32	8
530-0272	Tie wraps	3