

Index

Note: Page numbers in *italics* refer to figures and illustrations.

- Abbreviations
 - for machining operations, 29–30
- Abrasive sawing machines, 323, 323
 - abrasives for wheels, 324
 - cutoff saws, 303, 304
 - operation, 324, 324, 325
 - safety, 305, 306, 324
 - selecting, 324
 - wheel bonds, 324
 - wheel speeds, 324
- Absolute dimensioning, CNC, 671, 672
- Accuracy
 - in measurement, defined, 89
 - with micrometers, 131
 - when using steel rules, 107
 - with vernier calipers, 117–119
 - user accuracy, 89
- Acme cutters, 507–510
 - cutting on lathe, 507–510
- Acme forms, 502–503, 503
- Acme taps, 70, 70
- Acme thread gages, 507, 507
- Acme threads, 507–510
- Acme tool gages, 507, 507
- Acute angles
 - defined, 174, 174
 - measurement, 176
 - in right triangles, 178, 178
 - trigonometric functions, 257–258, 258
- Adjustable face spanner wrenches, 50, 51
- Adjustable hook spanner wrenches, 50, 51
- Adjustable parallels, 148–149, 149, 150
 - use with sine bar, 180–181, 181
- Adjustable reamers, 64, 64
- Adjustable wrenches, 49, 50
- Air gages, 92–93, 93, 94, 95
- Alignment
 - of lathe centers, 415–450
 - measurement, defined, 88
- Alignment telescope, 101, 102
- Allen wrenches *See* Socket head wrenches
- Alloy steels, 17, 18
- Alloys
 - approximate melting points listed, 762
 - density and specific gravity, 761
- Aluminum, 203, 204
- American National form, 466, 466
- American National standard taper pipe thread, 468, 469
- Angle milling machine, 535–537
- Angle vise, 368, 368
- Angles
 - acute, 174, 174
 - arithmetic, reviewed, 175, 759
 - clearances, on milling cutters, 557, 645, 646
 - face milling cutters, 582–583
 - on lathe tools, 405–406, 405
 - terms and definitions, 406
 - layout calculations, 260
 - nose radius, 406, 406
 - obtuse, 174, 174
 - right, 174, 174
 - right-hand and left-hand, 406–407, 406
 - in right triangle, 257–258, 258
 - tapers and (chart), 758
- Angular measurement units, 174–175
- Angular measuring instruments
 - bevel protractors, 175, 176
 - plate protractors, 175, 176
 - sine bars, 178, 180–181
 - sinometer angle gages, 175, 176
 - universal bevel vernier protractors, 176–177, 176
- Angularity, defined, 89, 89
- Annealing
 - of band saw welds, 328–329, 329
 - normalizing and stress relieving, 221–223
- Apprentice machinists, 4
- Aprons, on engine lathes, 392–393, 394
- Arbor driven cutters
 - plain types, 556, 556, 557
 - side milling types, 557–560
- Arbor presses, 37, 38
 - uses of, 37–38, 38
- Arbors
 - horizontal mill, 553–555
 - setup, 571–572, 572
 - spacing and bearing collars, 553, 554
 - for lathe, 444, 444
 - support bearings, 554–555, 554
- Arc versus chord length errors, 158, 159
- Area measurement rules, 759
- Arithmetic average, 190
- Assembly drawings, 28
- Autocollimators, 101, 101
- Automotive machinists, 4
- Auxiliary views, on drawings, 27–28, 28
- Babbitt metals, 206, 206
- Back spotfacing, 375, 376
- Balancing, of grinding wheels, 609–610, 610
- Ball and roller bearings, 39
- Ball-bearing lathe centers, 435–436, 437, 437
- Ball peen hammers
 - for layout, 238, 239
 - machinist's, 48–49, 49

- Band blade welders, 326, 326
- Band machines
 - advantages, 306–307
 - high-tool velocity types, 309, 309, 310
 - horizontal, 302, 302
 - large-capacity type, 309, 310
 - types of, 308–309
 - vertical, 306, 308, 308
- Band machining, 306–307
- Band saw welding, 326
 - annealing welds, 328–329, 329
 - grinding welds, 329, 329, 330
 - horizontal, safety, 304
 - preparation of blade, 326–327, 328
 - problems, 329, 330
 - safety, 328, 328
 - vertical, safety, 311, 311–312, 312
- Bar chucker, CNC, 661, 662, 662
- Base, vertical mill, 514
- Bastard cut files, 59, 60
 - coarseness, 57, 57
- Bearing pullers, 39, 39
- Bearings, four types of, 716
- Bed, engine lathe, 392, 394
- Bed-type horizontal mill, 546
- Beryllium copper, 205
- Bevel protractors, 175, 176
- Bilateral tolerances, 28
- Bills of materials, on drawings, 31
- Blocks, CNC programs, 676–681
- Blueprinting, of drawings, 30
- Bolster plates, on shop presses, 39
- Bolt circles, geometric construction layout, 248–249
- Bolts
 - abbreviations on drawings, 30
 - carriage, 17, 17
 - defined, 16
 - diameter of bolt circle (D.B.C. or B.C.), 30
 - grade marking for, 19
 - head markings, 19
 - machine, 17, 17
 - stud, 17, 17
 - types, 17
- Bore gage expansion plug, 94, 96
- Bores and shafts, 39–40
- Boring
 - blind hole, 455, 455
 - CNC cutting tools, 709, 710, 710
 - in lathe, 453–456
 - thread relief, 455–456, 456
 - through boring, 454–455, 455
- Boring bars
 - engine lathe, 403–404, 404
 - for lathe
 - setup positions, 454, 454, 455
 - types, 453, 453
 - toolholder, 400, 400
- Bottoming taps, 67–68, 68
- Box end wrenches, 49–50, 50
- Brass, 205
- Bridge reamers, 378–379, 378
- Brinell Hardness tester, use of, 231–233
- Broach
 - keyway broaching, 40–42, 41
 - guide for, 41, 41
 - production broaching, 42, 43
 - push broaching recommendations, 42
- Bronze, 205
- Bushings
 - guide, for pressing, 39, 39
 - installing, 38–39, 39, 40
 - special tooling, 39, 39
- C-clamp, 367, 368
- C-clamp body
 - drilling procedure, 370–372
- C-clamp tools, 47, 47, 48
- CAD/CAM (Computer Aided Design and Manufacturing), 2
 - part programming with, 698–699
- Cadmium, 204–205
- Calibration
 - defined, 131
 - in measurement, 91
 - micrometers, 131
 - use of gage blocks, 139, 140, 161, 162
- Calipers
 - dial, 123, 123
 - electronic (digital), 123–124, 124
 - hermaphrodite applications of, 238, 238
 - inside micrometers, 127, 127
 - outside micrometers, 130, 130
 - slide, 108, 109
 - spring, 146, 147
 - vernier, 117–119
- CAM (Computer Aided Manufacturing), 2
 - part programming with, 698–699
 - post-processor, 699, 700
- Camlock spindle nose, for lathe, 414, 414
- Capscrews, 17, 19
- Carbide face mills, 584, 584
- Carbide inserts, identification, 292, 296
- Carbide toolholders
 - identification systems, 292, 295, 296
- Carbide tools, 284–294
 - new technology, 294
 - selection of, 285–292
- Carbide-tipped chucking reamers, 379, 379
- Carbide-tipped helical flute chucking reamers, 379, 379
- Carbide-tipped straight flute chucking reamers, 379, 379
- Carriage bolts, 17, 17
- Carriages, engine lathe, 392–393, 394
- Carrying objects, safety aspects, 11–12
- Case hardening and tempering, 209–220
 - of steels, 215, 215–217
- Cast iron surface plates, 236, 236
- Cat heads, 498, 499, 500
- Cemented carbide cutting tools, 284–285
- Center drilling, lathe, 432, 432–433, 433
- Center drills, 350, 351, 366, 370, 373
 - countersinks, 374, 374
- Center punches
 - automatic center, 239, 240
 - center, 239, 239

- hollow grinding, 83, 84
- optical, 239–240, 240
- Centers
 - dead, for lathe, 435, 437, 437
 - lathe, 428, 429, 432–433
 - lathe tailstock, 435–436, 436, 437
 - live, for lathe, 435–436, 436, 437
- Centerhead
 - machinist's combination square set, 152–154, 152
 - round stock center layout, 240, 241, 497
- Centerless grinders, 589–591
- Center-type cylindrical grinders. *See* Cylindrical grinders
- Ceramic tools, 288, 294, 297
- Cermets, 297
- Chamfer bushing bores, 39–40, 40
- Chamfer tap, 67, 67
- Chamfers
 - reading drawings, 29
 - symbols, 31
- Chatter, in boring operations, 453–454, 453, 454
- Chemical safety, 6–7
- Chip breakers
 - cemented carbide inserts, 292, 292, 293
 - CNC, 706, 706
 - Kenloc Chip-Control insert application, 294
 - for lathe tools, 409–410, 409
 - types of, 273, 274
- Chip control
 - lathe, 409–410, 409
 - milling machine, 574
- Chip formation, 266, 269, 270–271
 - safety when turning, 442, 442
- Chip removal, CNC, 667
- Chip structure analysis, 271–273
- Chisels
 - hollow grinding, 83, 84
 - types, 52, 53
- Chromium, 205
- Chucks
 - drill press, 350, 350
 - independent four-jaw, for lathe, 414, 415
 - installing camlock type, on lathe, 425, 426–427
 - magnetic
 - lathe, 416, 417
 - surface grinder, 621–622, 621, 622
 - vertical spindle milling machine, 525–526, 526
 - six-jaw, for lathe, 414, 415
 - tailstock, for lathe, 432, 432
 - three-jaw universal, for lathe, 414–416, 415, 415
 - two-jaw universal, for lathe, 414, 415
 - vacuum, for surface grinders, 622, 622
- CIM (Computer Integrated Manufacturing), 2
- Circular interpolation
 - CNC, 686–688, 688
- Circularity, defined, 88
- Circumference, general measurement techniques, 759
- Clamps
 - C types, 47, 47, 48
 - parallel, 47, 47
 - strap, 366, 367
- Clearance angles, on milling cutters, measurement, 645, 647
- Climb milling
 - angles, 583, 583
 - horizontal mill, 571, 572
 - vertical mill, 530
- CNC (Computer Numerical Control)
 - absolute dimensioning systems, 671, 672
 - adaptive control (AC), 717–718
 - advantages and capabilities, 660
 - angular interpolation, 683, 683
 - automatic tool changer (ATC), 663, 663, 676, 677, 714–715
 - CAD and CAM, 660
 - chip removal, 667
 - circular interpolation, 686–688, 688
 - color graphics, 667
 - contour machining, 663, 665, 666
 - coordinate tables, for drilling, 680
 - cutter compensation, 685–686, 686
 - developing programs, 676–681
 - electrodischarge machining (EDM), 661
 - flexible manufacturing systems, 664, 667
 - fundamental programmable axes, on machine tools, 670–671
 - G code table, 675
 - helical milling, 663, 667
 - history, 660
 - horizontal spindle machining center, 663, 664, 667, 670, 670, 671
 - human and robot-operated, 2
 - incremental positioning systems, 671, 672
 - laser, 661, 661, 722
 - linear interpolation, 681–682, 681
 - miscellaneous function commands (M codes), 674
 - modal commands, 674, 675
 - operating the machine tool, 702–703
 - parabolic and cubic interpolation, 688
 - polar coordinates, 668, 669, 670
 - position dimensioning systems, 668–672
 - preparatory function commands (G codes), 674, 675, 676
 - program blocks, 676–681
 - programmable axes, 668–672
 - programmable rotary table, 663, 666
 - programmable rotational axes, 671
 - quadrants, 668, 669
 - safety, 665, 666
 - single-point threading, 663, 666
 - standard programming code, 674
 - tapping, 688–689
 - tool and cutter grinding, 656, 658
 - tool coatings, 706
 - tool materials, 705
 - tooling, 705–717
 - turning centers, 661, 662
 - turn/mill centers, 661, 662
 - types and capabilities of machine tools, 661, 662, 663–667
 - vertical spindle machining centers, 663, 663, 664, 665
 - X-Y plane, 668–669, 669
 - X-Z plane, 669
 - Y-Z plane, 669
 - Z-axis offsets, 670–671

- CNC cutting tools
 - boring, 709, 710, 710
 - coatings, 706
 - end mill ball nose chip thinning, 712–713, 713
 - end mill chip thickness, 711–712, 712
 - end mill rigidity, 713–714, 714
 - high-speed machining, 706–707
 - hole making, 707–708, 707
 - indexable drills, 708, 708
 - reaming, 709, 709
 - roller burnishing, 711, 711
 - spade drills, 709
 - tapping, 689, 709–710
 - trepanning, 709
- CNC dimensioning systems
 - absolute positioning, 671, 672
 - Cartesian coordinates, 668
 - coordinate tables, 679–680, 680
 - incremental mode, 671, 672
 - rectangular coordinates, 668, 669
- CNC programming
 - code, 674
 - drilling, 673–703
 - general technique, 673
 - methods, 673
 - offset files, 677
 - part programming with CAD/CAM, 698–699
 - programming example, 690–693
 - prompted programming systems, 699–702
 - single-point threading, 689–690, 697–698
 - turning, 690
 - codes, 693–697
- CNC tooling
 - adaptive control (AC), 717–718
 - EPRM offset data, 714–715, 715
 - high speed spindles, 715, 716
 - touch sensor inspections systems, 715, 715, 716
- Coatings, CNC cutting tools, 706
- Coaxial dial indicators, vertical mills, 527, 527
- Code, CNC programming, 674
- Cold saws, 303, 304, 325, 325
- Collet chucks, 418, 418
- Collet sleeves, 418, 418
- Collets
 - R-8, for milling machine, 521
 - rubber flex type, for lathe, 417, 417
 - solid, for vertical mill, 521, 521
 - split, 521, 521
 - spring type, 418, 418
 - steel-spring, for lathe, 417, 417
- Column, vertical mill, 514
- Combination center drill and countersink, 374, 374
- Combination square set, 152–154, 152
- Combination wrenches, 50, 50
- Comparator
 - dial indicator, 161–162, 162
 - electromechanical, 163–164, 164
 - electronic, 100, 100, 161, 161
 - micrometer, for threads measurement, 478, 478
 - optical, 101, 101, 161, 161
 - for visual surface roughness, 98, 98
- Comparison measuring instruments
 - adjustable parallels, 148–149, 149, 150
 - dial test indicators, 159–161
 - diemaker's square, 154, 154
 - indicators, 155–161
 - machinist's combination square, 152, 152
 - planer gage, 151–152, 151–152
 - precision beveled edge squares, 152–153, 153
 - profile projector, 163, 163
 - shop tip, 164
 - small hole gage, 148, 149–150
 - spring calipers, 146, 147
 - squares, 152–154
 - telescoping gages, 146–148, 147–149
 - thickness gages, 149–151, 151
- Compressed air, safety with, 10
- Computer Aided Design (CAD), 2, 3
 - part programming with, 698–699
- Computer Aided Manufacturing (CAM), 2
- Computer Integrated Manufacturing (CIM), 2
- Computer Numerical Control. *See* CNC (Computer Numerical Control)
- Concentricity, defined, 88
- Contour sawing
 - vertical band saws, 339–340, 340
- Contouring, with band saw, 307, 307, 310, 310
- Controls
 - on lathe, 420–424
 - clutch rod, 423, 423
 - feed rates, 421–424
 - quick change gear selector, 421, 422
- Conventional milling
 - horizontal mill, 571, 572
 - vertical mill, 530
- Conversion charts (metric), 105, 753–754
- Conversion dials, 105, 105
- Conversion factors, metric system, 104–105
- Coolant separators, 283
- Coolants listed, 765
- Coordinate layouts
 - height gage, 256–257
- Coordinate layouts, for hole patterns, 249, 256–257, 258–259
- Coordinate measurement, calculations, 256–257, 258–259
- Coordinate measuring machines, 98, 99
- Copper and copper alloys, 205
- Cosine error, 158, 159
- Cosine ratio, of acute angles defined, 257
- Counterbores
 - interchangeable pilots, 375, 375
 - multiflute, 375, 375
 - two-flute, 375, 375
- Counterboring
 - defined, 29
 - symbols, 30
- Countersinking
 - defined, 29
 - symbols, 30
- Countersinks, 374, 374
- Crazing, prevention of, 293
- Crescent wrench, 49, 50
- Cross peen hammers, 49, 49

- Cubic boron nitride (CBN), 599, 599
 - truing, 607–608, 608
- Cubic boron nitride (CBN) cutting tools, 294, 297
- Curved tooth files, 59, 59
- Cutoff lathe tools, 407–409
- Cutoff machines
 - cold saws, 303, 304, 325, 325
 - safety, 306, 306
 - horizontal band saws, 302, 302, 303
 - reciprocating saws, 302
 - tilt frame band saws, 302–303, 303, 304
- Cutoff toolholders, engine lathe, 403, 403
- Cutter compensation, 685–686, 686
- Cutters
 - Acme threads, 507–510
 - arbor driven, for horizontal mills, 556, 556–561
 - carbide, for lathe, 285–297, 405, 405
 - face milling, horizontal mill, 581–584
 - hand grinding, 410–412
 - high speed, lathe, 405–407
 - involute gear cutters, 560–561, 560
 - lead angle, 582, 582
 - re-sharpening milling types, 650–656
 - turning unified threads, 470–471
 - types, 407–409, 410
 - vertical milling machine, 517–521, 521
 - Woodruff key, 519, 519
- Cutting fluids, 765
 - application methods, 281–283
 - cutting oils, 280–281, 765
 - drilling machines, 364
 - effects, 279–280
 - emulsions, 280
 - gaseous fluids, 281
 - for grinding, 604, 605, 612–616
 - grinding machines, 364
 - metal cutting, 264–265, 266, 270
 - sawing with, 315
 - semisynthetic fluids, 280
 - synthetic fluids, 280
 - types, 280–281
 - vertical band saws, 339, 340
- Cutting speeds (CS), 275–277
 - calculations
 - drill press, 362–363
 - for commonly used materials, 531, 531, 765
 - defined, 530–531
 - drilling, 362–363
 - horizontal milling machine, 567
 - lathe, 439–441
 - sawing, 313
 - vertical milling machines, 530–531
- Cutting tools
 - cemented carbides, 284–285
 - ceramics, 288, 294, 297
 - clearance, 294, 297
 - cubic boron nitride, 294, 297
 - diamond, 298
 - drill press, 349–357
 - engine lathe, 405
 - form cutters, 407, 407
 - high speed steels, 405–407
 - high-carbon steels, 284
 - horizontal mill, 556–561
 - materials, 284–298
 - vertical mill, 517–520, 521
- CVSG grinding abrasive, 600
- Cyanogen compounds
 - precautions, 6
- Cylindrical grinders
 - accessories, 640
 - capabilities, 637–639, 640
 - major parts, 635–637, 635
 - mandrel grinding, procedure for, 643–644
 - setup, 641–642, 643–644, 643
 - types, 588–592
 - workholding on, 637, 637
- Cylindrical ring gage, 91, 93
- Cylindrical squares, 153–154, 153, 154
- Dead lathe centers, 437, 437
- Decibels (dB), safety aspects, 8
 - level of various sounds, 9
- Decimal angles, 175
- Decimal equivalents. *See also* Metric
 - for drill sizes, 354–355
 - of fractional inches (table), 753
 - inch/metric conversion tables, 753–754
- Decimal notation, 112
- Decimal rules, 112–113, 113
- Deep hole drilling machines, 344, 344
- Depth gage
 - dial indicator type, 123–124, 123
 - vernier type, 121
- Depth micrometer
 - reading, 138–139, 139
- Depth micrometers, 138, 138
- Depth of threads, 466, 467
- Desmond dresser, 82
- Detail drawings, 28, 31
- Diagonal cutters, 48, 48
- Dial bore gages, 94, 96
- Dial calipers, 123, 123
- Dial depth gages, 123, 123
- Dial indicating expansion plug bore gages, 94, 96
- Dial indicating inprocess grinding gages, 95, 97
- Dial indicating screw thread snap gage, 94
- Dial indicating screw thread snap gages, 94, 97
- Dial indicating snap gages, 94, 95
- Dial indicating thread plug gages, 94, 97
- Dial indicators
 - care and use of, 156–157, 157
 - depth gages, 123–124, 123
 - potential for error, 157–158, 159
 - types, 155, 155–161, 156
- Dial instruments, shop tip, 123
- Dial test indicators, 157, 157
 - use of, 159–161
- Dial thickness gages, 93, 95
- Diamond, as superabrasive, 599–600, 599, 604
- Diamond cutting tools, 298
- Die sinker's riffler files, 59, 59
- Die threading
 - by hand, 79–80

- Die threading (*Continued*)
 - on lathe, 79, 79, 459, 459
- Die-cast metals, 205–206, 205
- Diemaker's squares, 154, 154
- Dies
 - blanks, 77, 78
 - button, 77
 - markings, 77, 77
 - rethreading type, 78, 78
 - solid square, 78, 79
 - thread cutting, 77–80
 - two-piece, 77, 78
- Diestock, 77, 78
- Digital readout (DRO)
 - horizontal mill, 547, 547
 - vertical mill, 106, 106, 529, 529
- Dimensional metrology, 88
- Dimensioning systems, in drawings, 28, 28
 - coordinate or absolute, 29, 29
 - decimal inch notations, 29, 29
 - dual system, 29, 30
 - standard tolerances, 28
 - tolerances, 28
- Direct-reading micrometers, 127, 127
- Discrimination
 - 10:1 rule, 90
 - in measurement, 90
 - micrometers, 131
 - steel rules, 107
- Disk micrometers, 125, 126
- Dividers, for layouts, 237–238, 238
- Dividing heads, 564, 564
- Dovetails
 - machining, 535–537
- Draw filing, 61, 61
- Drawings
 - assembly, 28, 31, 32
 - auxiliary views, 27–28, 28
 - bill of material, 31
 - blueprinting, 30–31
 - change blocks, 31, 31
 - detail, 28, 31
 - dimensioning systems, 28
 - exploded, 26, 27
 - finish, marks on, 29, 30
 - formats, 30–31, 32
 - hidden lines, 26–27, 27
 - isometric, 26, 27
 - oblique, 26, 27
 - orthographic format, 26–28, 27
 - pictorial formats, 26
 - precision vise project drawings, 766–769
 - reading and interpreting, 28–31
 - sectioned views, 27, 28
 - title blocks, 30, 31, 31
- Dress safety, 8
- Dressing
 - grinding wheels on pedestal grinders, 82, 83
 - surface grinder wheels, 606
- Drift punch, for drill sleeve, 353, 356, 356
- Drill and hole gage layout, 244–247, 248
- Drill chucks, for lathe tailstock, 401, 402
- Drill grinding procedure, 359–361
- Drill presses
 - chucks, 350, 350
 - cutting tools, 349–357
 - deep hole, 344, 344
 - heavy duty, 342
 - micro, 342, 343
 - procedures, 364–366, 365, 366
 - radial arm, 342, 342, 346, 347, 348, 348
 - reaming with, 65–66, 65
 - safety, 344–345
 - sensitive, 342, 342, 346, 346
 - table, 342
 - turret, 342, 343, 343
 - types, 342–344
 - upright, 342, 342, 345, 346–347, 348
 - vises, 367–368, 368
 - workholding, 366, 367, 368–371
- Drilling
 - angle plates, 367, 368
 - C-clamp body, procedure, 370–372
 - jigs and fixtures, 370, 371
 - lathe, procedures, 364–366, 365, 366, 451–452
 - pecking, 364
- Drilling machines, operation, 362–373
- Drill point gages, 358, 358, 361, 361
- Drill pointing machines, 356, 357
 - split-point design, 356, 357
- Drills
 - accuracy of drilled holes, 356
 - burnishing, 350
 - center, 350, 351
 - drill sizes, decimal equivalent tables, 354–355
 - gun, 352, 352
 - hand grinding, 359–361
 - hard steel, 352, 352
 - high-helix, 349, 350
 - high-speed, 349
 - jobber's, 350
 - left-hand, 349, 350
 - low-helix, 349, 350
 - major parts, 349
 - oil hole, 350
 - selection, 351–353
 - size series, 353
 - spotting, 349, 351, 351
 - standard helix jobbers, 349
 - step, 351, 351
 - tap, 72–73, 73
 - taper shank, 349
 - three-flute, 349
 - twist, 351, 352
 - twist, parts of, 349–350, 349, 350
 - types, 349–351
- Drive plates, 417, 417
- Drives
 - back gear systems, for lathe, 420–421
 - band saws, 336, 337
 - lathe headstock, 420, 421
 - variable-speed, 420, 420

- Ear protection, sound suppressors for, 8, 8
- EBM machining, 720
- ECM machining, 721, 721
- Edgefinder, use on vertical mill, 526, 526
- EDM machining, 74, 718–720
 - CNC, 660
 - as tap disintegrator, 74
- Electrical safety, 11
- Electrochemical machining (ECL, ECDB), 721, 721
- Electrodischarge machining. *See* EDM machining
- Electrolytic grinding (ELG), 720
- Electromechanical comparators, 163–164, 164
- Electron beam machining (EBM), 720
- Electronic calipers, 123–124, 124
- Electronic comparators, 100, 100, 161, 161
- Electronic digital comparators, 161, 161, 163–164, 163
- Electronic digital travel indicators, 99–100, 99, 100
- Electronic micrometers, 130–131, 131
- ELG grinding, 720–721
- ELG machining, 720–721
- End mill ball nose chip thinning tools, 712–713, 713
- End mill chip thickness tools, 711–712, 712
- End mill holders, 521, 521
- End mills
 - ball end, 519, 519
 - checking cutting edges, 533
 - corner rounding, 519, 519
 - dovetail, 519, 519
 - four-flute, 517–518
 - helical flute, 518, 518
 - high-speed steel feeds, 765
 - high-speed steel helical, 518, 518
 - indexable, 520, 520, 521
 - leaning slots, causes for, 532, 532
 - roughing, 518–519, 519
 - sharpening, 654–656, 657
 - shell, 535, 536
 - single-angle dovetail, 519, 519
 - size markings, 535
 - straight flute, 518, 518
 - tapered, 519, 519
 - three-flute, 517
 - t-slot, 519, 519
 - two-flute, 517, 518
 - Woodruff key, 519, 519
- Engine lathes, 391
 - aprons, 392–393, 394
 - beds, 392, 394
 - boring bars, 403–404, 404
 - carriage, 392–393, 394
 - parts, 392–394, 392
- Engineers, professional, 4
- English system of measurement, 103–104
- EPROM offset data, 714–715, 715
- Expansion fits, 185
- Expansion plug bore gage, 94, 96
- Expansion reamers, 64, 64
- External threaded fasteners, 16–21
- Eye protection, 6, 7, 8
- Face driver, for lathe, 417, 417
- Face milling, 538–539
- Face milling cutters
 - horizontal mill, 581–584
 - use of, 581–584
- Face plate for lathe, 417, 417
- Face shields, 7, 8, 8
- Facing
 - on lathe, 425–430, 431
 - offset boring head, 542, 543
 - setup, 425–427
- Feathered key, 25
- Feed rates calculations
 - horizontal milling machines, 567–569
 - vertical milling machines, 531–532
- Feeds
 - breakage and, 264
 - calculations, 277–278
 - drilling, 363, 363, 364
 - high-speed steel end mills, 765
 - in metal cutting, 266
 - milling, 567–568
 - reaming, 379–380
 - turning, 439–441
- Files
 - bastard cut, 57, 57, 59, 60
 - card for cleaning, 60, 60
 - care and use, 60–62
 - curved tooth type, 59, 59
 - die sinker's rifflers, 59, 59
 - flat, 58, 58
 - half-round, 59, 59
 - handles, 60–61, 61
 - knife, 58, 58
 - lathe, 58, 58
 - major parts, 57, 57
 - mill, 58, 58
 - pillar, 58, 58
 - pinning, 60
 - round, 59, 59
 - square, 58, 58
 - Swiss pattern, 59, 59
 - tang, 57
 - thread repair, 59, 60
 - three square, 59, 59
 - types, 57–60
 - warding, 58, 58
- Finish marks, on drawings, 29, 30
- Fire extinguishers, 10–11
- Fits, shrink and expansion, 183, 185
- Fixed face spanner wrenches, 50, 51
- Fixed gages, 91, 92
- Fixed thread gages, 91, 92
- Flash chrome plating, 71
- Flat files, 58, 58
- Flatness, defined, 88
- Flexible Manufacturing System (FMS), 3, 664, 667
- Flycutters, 520, 520
- Follower rests
 - for lathes, 500
 - use of, 500

- Foot protection, 7–8
- Footstock, horizontal milling machines, 564, 564
- Form cutters, for lathe, 407, 407
- Four-jaw chuck
 - centering workpiece, 426
 - for lathe, 414, 415
- fpm (feet per minute), 313
- Friction sawing, 310, 311
- Fumes, control of, 6
- Furnaces, for heat treating, 212–213

- G code table, 675
- Gage blocks
 - applications, 171–172, 172
 - calculating stack height, 170–171
 - checking surface, with optical flats, 169, 169, 170
 - preparation for use, 167–168
 - preparing for storage, 170
 - sets with accessories, 164, 164
 - tolerances, 167
 - types and grades, 166
 - use with sine bar, 180–181, 181
 - value of, 167
 - wear blocks, 171, 172
 - wringing, 167–168, 169
- Gages
 - adjustable limit snap gages, 91, 92
 - air, 92–93, 93, 94
 - air plug, 92, 94
 - bore, 94, 96
 - CNC tool length, 678, 678
 - column (flow-type), 92, 94, 95
 - cylindrical plug, 91, 93
 - cylindrical ring, 91, 93
 - fixed, 91, 92
 - fixed thread, 92
 - go and no go, 79, 91
 - height. *See also* Height gages
 - for layout, 242, 242–243, 243
 - planer, 151–152, 151–152
 - for layout, 151–152, 151–152, 242, 243
 - plug, 94, 97
 - precision height gages, 159–160, 160
 - pressure-type air snap gages, 92, 94
 - radius, 149, 151
 - rule depth, 109–110, 109, 110
 - saw blades, 314, 314
 - screw pitch, 466
 - small hole, 148, 149, 149–150
 - snap, 91, 92
 - standard hook, 108, 108, 109
 - surface, 240–241
 - for layout, 240–241
 - taper plug, 91, 92
 - taper ring, 91, 92, 492–493
 - telescoping, 146–148, 147–149
 - thickness, 149–151, 151
 - thread plug, 91, 92, 483, 483
 - thread ring, 91, 92, 477, 477
 - thread roll snap, 477, 478
 - wire gages and metric equivalents, 764
- Galling, prevention of, 364
- Gang drill presses, 342, 343
- Gantry vertical spindle machining center, CNC, 663, 664
- General machinists, 3–4
- Geometric construction layouts
 - for bolt circles, 248–249
- Geometric dimensions, 186–187
- Geometric tolerances
 - concentricity notations, 186
 - datum and basic dimensions, 186–187
 - drawing formats for, 187, 188–189
 - feature location notations, 186
 - least material condition (LMC), 187
 - maximum material condition (MMC), 187
 - orientation notations, 186
 - regardless of feature size (RFS), 187
 - symmetry notations, 186
 - true position, 186
- Gib adjustment screws, 516, 516
- Gib head keys, 25
- Grade markings, on bolt heads, 19
- Grades
 - gage blocks, 166, 167
 - surface plates, 236
- Granite surface plates, 236, 236
- Grinders. *See* Grinding machines
- Grinding, CBN-plated grinding process, 548
- Grinding dust
 - collectors, 6, 7
 - health hazard, 6
- Grinding fluids
 - application methods, 613–614
 - cleaning, 614–615
 - grinding waste disposal, 615
 - steps to follow, 616
 - types, 604, 612–613
 - straight oil, 613
 - water-soluble chemical types, 612
 - water-soluble oil types, 612–613
- Grinding machines
 - abrasive processes, 593–595
 - adaptive machine controls, 593
 - centerless, 588, 589–591
 - cost effectiveness, 593
 - cylindrical, 588–592, 591
 - electrolytic, 720–721
 - fluids for, 612–616
 - free abrasive, 594, 594
 - gear finishing, 592–593, 592, 593
 - lapping and honing, 594, 594
 - superfinishing, 594, 595
 - pedestal, 81–84
 - See also* Pedestal grinders
 - roll-type, 588–589, 590
 - safety, 595
 - selection and identification, 598–605
 - superabrasives, 593–594
 - surface, 586–587, 588
 - See also* Surface grinders
 - thread grinders, 592, 593
 - universal tool and cutter, 591–592, 592
 - vibratory deburring, 594, 595
- Grinding twist drills, 358–361

- Grinding wheels
 - balancing of, 609–610, 610
 - concentration, 600
 - FEPA and U.S. sizes compared, 602–603
 - radius and form dressing, 609, 609, 610
 - ring testing, 81–82, 82, 595–596, 596
 - size and shape, 600, 600, 601
 - standard wheel marking systems, 600–602
 - truing and dressing, 606–609
 - types of abrasives, 598–600
- Groove micrometers, 130, 130
- Grooving, on lathe, 459–461
- Guide for broaching, 41, 41
- Gun drills, 352, 352
- Gun taps, 68, 68
- Hacksaws
 - blade sets, 54, 55
 - cuts on workpiece, 56, 56
 - hand, parts, 54–55
 - power, 302
 - use of, 55–56
- Half round files, 59, 59
- Hammers
 - ball peen, 48–49, 49
 - cross peen, 49, 49
 - for layout, 238–239, 239
 - lead, 49, 49
 - maul, 48, 48
 - soft, 49, 49
 - straight peen, 49, 49
 - toolmaker's, 239, 239
- Hand grinding, of drills, 358–361
- Hand grinding cutters, 410–412
- Hand protection, 9
- Hand reamers, 63–66
 - adjustable, 64, 64
 - helical flute, 64, 64
 - major parts, 63
 - Morse taper socket, 64–65, 64, 65
 - spiral flute taper pin, 64, 64
 - straight flute, 64, 64
 - use of, 65–66
- Hand tap wrenches, 50, 52
- Hand tappers, 72, 73
- Hand tools
 - hacksaws, 54–56
 - safety, 36
- Hardening of metals, 209–210, 210
- Hardness, measurement of, 225, 226
- Headstock spindle, engine lathe, 391–392, 392
- Heat treating
 - case hardening, 215–217
 - furnaces for, 212–213
 - problems during, 217–220
 - quenching media, 213–214, 215
 - safety, 196
 - of steels, 210–212
 - tempering, 215–217
- Height gages
 - checking zero reference, 252–253
 - by coordinate measure, 256–257
 - dial, 242, 242
 - digital, 242, 242
 - gage blocks, 242, 243
 - mechanical dial, 251, 251
 - scribers, 250, 251
 - vernier, parts, 250
- Helical flute hand reamers, 64, 64
- Helical milling, CNC, 663, 667
- Helix angle, of threads, 468, 468
- Helpers, 4
- Hermaphrodite calipers, 238, 238
- Hidden lines, on drawings, 26–27, 27
- High speed bearings
 - types of bearings, 716
- High speed lathe cutters, 405–407
- High speed lathe tools
 - angle degrees for, 409
- High speed spindles, 715, 716
 - types of bearings, 716
- High-carbon steels, 284
- High-velocity band machines, 309, 309, 310
- Hole making cutting tools, 707–708, 707
- Hook rule, 108, 108, 109
- Hook spanner wrenches, 50, 51
- Horizontal band machines, 302, 302, 303
 - plate saws, 302, 303
 - safety, 304–305, 304, 305
- Horizontal band saws, 316
 - installing blades, 315–316, 319, 320
 - operation, 316–317, 318
 - sawing problem, 320–321, 321
 - workholding, 318, 319
- Horizontal milling machines
 - arbor setups, 571–572, 572
 - arbor support bearings for, 554–555, 554
 - arbor types, 553–555
 - attachment and accessories for, 547–548
 - backlash eliminator, 546, 546
 - bed type, 546
 - controls, 550–551
 - cutters, 556–561, 559–560
 - cutting fluids, 569
 - digital readout (DRO), 547, 547
 - footstock for, 564, 564
 - horsepower calculations, 568–569
 - keyseat milling, 579–580
 - knee and column, 546
 - large CNC machining center, 547, 547
 - locks, 551
 - major parts, 549, 550
 - milling cutters, 556–561
 - plain milling, 567, 572–574, 574
 - rotary tables, 564, 564
 - routine maintenance, 551–552
 - safety, 548
 - setup, 567, 569–571
 - side milling, 577–580, 580
 - size, 549
 - spacing and bearing collars, 553, 554
 - spindle tapers, 553, 554
 - squaring workpiece, procedure, 574–575, 575–576, 575, 576
 - straddle milling, 580, 580

Horizontal milling machines (*Continued*)

- table, 546, 549, 549, 562–563, 563
 - types, 546
 - wipers to protect accuracy, 551
 - workholding, 562–566, 569, 570–571
- Horizontal spindle machining centers,
CNC, 663, 664, 667, 670, 670, 671
- Horizontal spindle surface grinders. *See* Surface grinders
- Horseplay in the shop, 9–10
- Hot metal safety, 196
- Housekeeping, in machine shops, 10
- HSS cutting tools, 284
- Hub micrometers, 127, 127
- Hydraulic presses, 37, 37
- Hydrojet machining, 721, 721
- Hypotenuse, in right triangle, 178

Inch/metric conversion tables, 753–754

- Indexable drills, 708, 708
 - Indicating micrometers, 127, 127
 - Indicating mill vise, procedure, 569–570
- Indicators
- dial and dial test, 155–161, 157
 - electronic digital travel, 99–100, 99, 100
 - surface finish, 98, 99, 99
- Infeed, 266
- Inserts, carbide, identification, 292, 296
- Inside micrometer calipers, 127, 127
- Inside micrometers, 136–138
- Inspectors, 4
- Interchangeable anvil micrometers, 127–128, 128
- Interference (press) fit, bushings, 39
- Interference fringes, 169, 170
- Interlocking joint pliers, 47, 47
- Internal infeed, calculation for threading, 482
- Internal micrometers, 127, 128
- Internal thread inserts, 21–22, 23
- Internal threads, cutting, 481–483
- Internally threaded fasteners, nuts, 20–22
- International System of Units (SI), 104
- Interrupted thread taps, 68, 68

Jig boring, 512

Job opportunities, 2–4

Job selector

- horizontal band machines, 315, 315
- vertical band machines, 336, 337

Just-in-time production, 516

Kerf

- handsaws, 54, 55
- of saw blades, 313, 314

Keys

- feathered, 25
- gib head, 25
- square, 25
- taper, 25
- Woodruff, 25

Keyseats

- bores and shafts, 39–40
- defined, 37–38

Keyways

- broaching, procedure for, 40–42
- milling
 - horizontal mill, 579–580
 - vertical mill, 535, 535

Knee and column

- horizontal mill, 546
- vertical mill, 514

Knife files, 58, 58

Knurling, on lathe, 461–463

- toolholder types, 461, 461, 462

Knurling tool, on lathe, 403, 403

Large capacity band machines, 309, 310

Laser interferometer, 101, 102

Laser machining, 722, 722

Lathe centers

- alignment, 415–450
- ball bearing, 435–436, 437
- dead, 435–436, 437
- half center, 430, 431
- pipe and tube, 437, 437
- types, 435–437

Lathe cutters

- Acme threads, 507–510
- hand grinding procedure for, 410–412

Lathe dogs, 435, 435, 437–438, 438

Lathe files, 58, 58

Lathe operations

- boring, 453–456
- center drilling, 432–433
- drilling, 400–401, 432–433, 451–453
- facing, 425–427
- grooving, 459–461
- knurling, 461–463
- parting, 459–461
- reaming, 456–457, 458
- recessing, 459–461
- tapping, 458–459
- threading, 470–480, 471–475
- toolposts, 399–400, 399, 400
- turning, 435–437

Lathes

- apron, 392–393, 394
- automatic, with CNC, 384–385
- backlash compensating adjustments, 396, 396
- bed, 392, 394
- camlock spindle nose, 414, 414
- carriage, 392–393, 394, 491, 491
- chip control, 410
- cleaning the lead screw, 395, 395
- CNC chucks, 385, 386
- cutting fluid applications, 281–282
- cutting speed calculations, 439–441
- dead centers, 435–436, 437, 437
- files, 59, 59
- floturn, 385, 386
- follower rest, 500
- gib adjustment, 395–396, 396
- headstock, 391–392, 392
- headstock spindle, 391–392, 392

- independent four-jaw chucks, 414, 415
- internal threading, 481–483
- magnetic chucks, 416, 417
- maintenance and adjustments on, 395–397
- on-site machining, 387, 387
- saddle, 392
- safety, 387–390
- setup, for threading, 471–472
- six-jaw chucks, 414, 415
- spindle, 392, 413–416
- spindle tooling, 413–418
- steady rest, 496–499
- swing, measurement, 394
- tailstock, 393–394, 394, 396–397, 397
- tracer, 385, 386
- types, 384–386
- vertical boring mills, 384, 385
- ways, 392
- Layout
 - accessories for, 243, 243
 - basic precision practice, 255–259
 - clamp frame, 255, 255, 256
 - classifications, 236
 - dividers, 237–238, 238
 - drill and hole gage, 244–247, 248
 - dyes, 237, 237
 - geometric construction for bolt circles, 248–249
 - position-one, 255, 255–256
 - position-three, 255–256, 256, 257
 - position-two, 255, 256
 - precision practice, 250–260
 - preparation of workpiece, 244
 - round stock center, 497
 - scribers for, 237–238, 237
 - semiprecision, 244–249
 - tables, 236
 - tools for, 236–243
 - trammel points for, 238, 238
- Layout punches, 239–240, 240
- Layout tables, 236
- Layout tools
 - reshaping, 83
- Lead and lead alloys, 206, 206
- Least material condition (LMC), 187
- Length, 88–89, 88, 89
 - measurement rules, 759
- Lifting and hoisting, 195, 195
 - techniques for safe, 9, 10
- Light, measurements with, 100–102
- Lighting, importance of, 525
- Limit dimensioning, 184
- Limited machinists, 4
- Linear interpolation
 - CNC, 681–682, 681
 - linear, CNC, 683, 683
- Lock-out tag-out procedures, 11
- Long taper spindles, for lathe, 413, 414

- M codes, CNC programming, 674
- Machinability, 266, 273–274
- Machine bolts, 17, 17
- Machine hazards, 12
- Machine operators, 2–3
- Machine reamers, 377–379. *See also* Reamers; Reaming
 - arbor, 378, 378
 - chucking
 - carbide tip, 379, 379
 - helical flute carbide tipped, 379, 379
 - helical flute, 377, 378
 - helical taper pin, 378, 378
 - jobber's, 377, 378
 - Morse taper, 378, 378
 - rose, 377, 378
 - shell, 378, 378
 - taper bridge, 378–379, 378
 - taper shank helical flute, 377, 378
 - taper shank straight flute, 377, 378
 - types, 377–379
- Machine reaming
 - cutting fluids, 380
 - problems, 380–381
 - stock allowance, 380, 380
- Machine screws, 17, 17
- Machine screws, head styles, 18
- Machine tools
 - CNC, 660, 661, 662
 - speeds and feeds, 275–278
- Machines, for layout, 242–243, 243
- Machining centers
 - CNC, 663, 663–664
- Machining operations defined, 267–269
- Magnesium, 206
- Magnetic chuck lathes, 416, 417
- Magnetic chuck surface grinder, 621–622, 621, 622
- Magnetic chuck vertical mill, 525–526, 526
- Maintenance machinists, 4
- Mandrel grinding procedure, 643–644
- Mandrels
 - expanding type, 444, 445
 - gang, 444, 445
 - stub, 444, 445, 446
 - taper, for lathe work, 444
- Marine machinists, 4
- Material Safety Data Sheets (MSDS), 7
- Materials
 - for cutting tools, 284–298
 - hot metal safety, 196
 - lifting and hoisting, 195, 195
 - safety in carrying, 195
 - safety in handling, 196
 - selection and identification of steels, 197–202
- Maul hammers, 48, 48
- Maximum material condition (MMC), 187
- Measurement. *See also* Decimal equivalents; Metric system
 - area, 759
 - by comparison methods, 146
 - decimal equivalents of fractional inches, 752
 - electronic, 98–100, 98
 - inch/metric conversion tables, 753–754
 - length, 759
 - reference points, 107

- Measurement. *See also* Decimal equivalents; Metric system systems, 103–106
of tapers, 492–494
of threads, 477–480
volume and capacity, 760
weight, 760
- Mechanical dial measuring instruments, 93–97, 93, 94
- Mechanical dial travel indicators, 95–97, 98
- Mechanical hardware, 14–25
- Metal cutting, principles of, 266–271
- Metals. *See also individual metals*; Nonferrous metals alloys, 194
approximate melting points listed, 762
classifying, 195
density and specific gravity, 761
hardening of, 210–212, 210
machinability, 273–274
oxidation reduction process, 194
safety, 6
space-age, 194
- Meters, 104, 759
- Metric mechanical dial travel indicators, 106, 106
- Metric rules, 113–114, 114
- Metric system of measurement, 104–105
dual dimensioning of drawings, 29, 30
equivalent measurements of length, 759
inch/metric conversion table, 753–754
volume and capacity, 760
weight, 760
wire gages and metric equivalents, 764
- Metric threads
basic designations, 751
forms, 469, 469
- Metrology, 88
dimensional, 88
general principles, 89–91
- Micro drill presses, 342, 343
- Micrometers, 29, 99
- Micrometer squares, 154, 155
- Micrometers
ball attachments, 130, 130
blade type, 125, 125, 126
caliper-type outside, 130, 130
carbide-tipped, 132
care of, 131–133
collars, on lathe, 422–423, 423
combination inch/metric, 125, 126
comparator type, 125, 126, 478, 478
depth type, 138–139, 138, 139
digital electronic, 130–131, 131
direct-reading, 127, 127
discrimination of, 131
disk type, 125, 126
groove type, 130, 130
hub, 127, 127
indicating bench, 98, 98
indicating type, 127, 127
inside, 127, 127, 136–138
interchangeable anvil, 127–128, 128
internal type, 127, 128
metric type, 139–142
outside, 130, 130, 191
point comparator, 125, 126
reading inch types, 133–134
reliability and accuracy, 131
screw pitch, 479
screw thread comparator, 125, 126
screw thread type, 128, 129
shop tip, 135
spline, 128, 128
square, 154, 155
taper, 130, 130
for taper measurement, 494, 495
thread comparator, 478, 478
tubing, 129–130, 129, 130, 139–130
turning to length, 444, 444
turning to size, 442, 442
types of, 125–131
using, 124–125
V-anvil, 129, 129
vernier, 143–144, 143
- Mill files, 58, 58
- Milling cutters
clearance angles, 645, 646, 647
horizontal milling machines, 556–561
safety, 557
sharpening, 647, 648
vertical milling machines, 517–521, 521
- Milling machine tapers, 485–494
- Miscellaneous function commands (M codes), 674
- Modal commands, CNC programming, 674, 675
- Modified square threads, form of, 500, 500
- Mold makers, 4
- Molybdenum, 206
- Morse taper drill sockets, 353, 356
- Morse taper reamers, 64–65, 64, 65
- Morse taper twist drills, 349–350, 350
- Morse tapers
dimensions for, 485, 486
drill chucks, 401, 402
drill sleeves, 353, 356
reamers, 378, 378
- MSDS (Material Safety Data Sheets), 7
- Multiple lead threads, cutting of, 503–506
- Multispindle drill presses, 343, 343
- Needlenose pliers, 48, 48
- Nickel, 206, 206
- Nickel-based alloys, 207
- Nonferrous metals
beryllium copper, 205
brass, 205
bronze, 205
cadmium, 204–205
chromium, 205
copper and copper alloys, 205
die-cast metals, 205
lead and lead alloys, 206, 206
magnesium, 206
molybdenum, 206
nickel, 206, 206
nickel-based alloys, 207
precious metals, 207
safety, 6

- selection and identification, 203–208
- tantalum, 207
- tin, 207, 207
- titanium, 207, 208
- tungsten, 208
- zinc, 208
- zirconium, 208
- Normalizing, 221–222, 221
- Nose
 - engine lathe spindles, 392, 393
 - lathe spindles, types, 413–416
- Nut taps, 70, 70
- Nuts, common types, 20–21, 21

- Oblique drawings, 26, 27
- Obtuse angles, defined, 174, 174
- Occupational Safety and Health Act (OSHA), 7, 12
- Offset boring heads
 - controlling bore diameters, 542
 - facing with, 542, 543
 - feeds and speeds, 542
 - parts of, 540, 541
 - setup, 541, 541
- Open ended wrenches, 49, 50
- Optical center punches, 239–240, 240
- Optical comparators, 101, 101, 161, 161
 - for thread measurement, 479, 480, 481
- Optical flats, 100–101, 101, 169
 - for checking gage blocks, 169, 169–170
- Orthographic drawings, 26–28, 27
- Orthographic projections, on drawings, 26, 27
- Outside micrometers, 130, 130, 191
 - care of, 131–133
 - major parts, 131

- Parabolic and cubic interpolation, 688
- Parallax errors, 110, 110
- Parallel clamps, 47, 47
- Parallels
 - adjustable, 148–149, 149, 150
 - drill press setup tools, 366–367, 367
 - in layouts, 254
- Parting, in lathe, 459–461
- Pedestal grinders
 - adjusting spark guard, 82, 82
 - adjusting tool rest, 82, 82
 - dressing wheel, 82, 83
 - for drill grinding, 358–361
 - replacing wheel, 81, 81
 - safety, 82, 84
 - setup, 81–82
 - using, 82–83, 82
- Percentage, of threads, 468
- Personal safety, 6–7
- Pillar files, 58, 58
- Pilots, for counterbore, 375, 375
- Pin punches, 52, 53
- Pins, types of, 24, 24
- Pipe and tube centers, 437, 437
- Pipe and tube lathe centers, 437, 437
- Pipe thread taps, 69, 69
- Pipe wrenches, 50, 51

- Pitch
 - bandsaw blades, 314, 314
 - diameter, of threads, 468, 468
 - hand hacksaw blades, 55, 55
 - screw threads, 466
- Plain milling, horizontal mill, 572–574, 574
- Planer gages, 151–152, 151–152
 - for layout, 242, 243
- Plasma beam machining, 721–722
- Plate protractors, 175, 176
- Plate saws, 302, 303
- Pliers
 - interlocking joint, 47, 47
 - needlenose, 48, 48
 - round nose, 47–48, 47
 - side cutting, 48, 48
 - slip joint, 47, 47
 - vise grip, 48, 48
- Plug gages
 - for taper measurement, 492–493
- Plug taps, 67, 68
- Plunge cutting, 533–534, 534
- Pneumatic comparators, 92–93
 - See also* Air gages
- Point comparator micrometers, 125, 126
- Polar coordinates, CNC, 669, 670
- Position dimensioning systems, CNC machines, 668–672
- Position, of linear measurement instruments, 90, 90
- Power fed worktables, on band machines, 308–309, 309
- Power hacksaws. *See* Reciprocating cutoff machines
- Precious metals, 207
- Precision
 - layout, 244–260
 - in measurement, 89–90
- Precision beveled edge squares, 152–153, 153
- Precision height gages, 159–160, 160
 - with gage blocks, 171, 173
- Precision measurements, 90
- Precision vise project drawings, 766–769
- Press fits
 - dimensional allowance for, 185
 - surface finish for, 185
- Presses. *See also* Drill presses
 - arbor, 37–38, 38, 41, 42
 - hydraulic, 37
 - mechanical, 37, 38
- Pressing
 - bearings, 39, 39
 - bushings, 38–39, 40
- Pressure-type air gages, 92, 93
- Prick punch, for layouts, 239, 239
- Primary clearance angles, milling cutters, 645, 647
- Process annealing, 222–223
- Product technicians, 4
- Profile projectors, 163, 163, 164
- Programmable axes, CNC machine tools, 668–672
- Programmable rotary table, 663, 666
- Programming, defined, 673
- Programming methods
 - CNC, 673
 - prompted programming systems, 699–702
- Projections, on orthographic drawings, 26, 27

- Pulley taps, 69–70, 70
- Punch layout, 239–240, 240
- Punches
 - drift, 353, 356, 356
 - pin, 52, 53
 - prick, for layout, 239, 239
 - types, 52, 53
- Quadrants, CNC, 668, 669
- Quenching media
 - heat treating, 213–215
- Quick change gear box, engine lathe, 394, 394, 422
- Quick change tool holders, engine lathe, 399–400, 399, 400
- Quick change tooling, drill press, 366, 366
- Quick change tooling system
 - for vertical mill, 521, 522
- R-8 collets, for milling machine, 521
- Radial arm drill presses, 342, 342, 347, 348, 348
 - major parts of, 347, 348, 348
- Radian measurement, 174–175, 174
- Radius gages, 149, 151
- Rake, on cutting tools, 266, 269
- Ram turret lathes, 384, 385, 386
- Ram vertical mills, 514, 515
- Ratios, trigonometric, 257
- Reading drawings, 26–32
- Reamers. *See also* Machine reamers
 - adjustable, 64, 64
 - carbide-tipped expansion, 379, 379
 - carbide-tipped helical flute chucking, 379, 379
 - chucking, 377, 378
 - hand, 63–66
 - machine, parts of, 377, 377
 - shell, 378, 378
 - taper pin, 378, 378
- Reaming
 - CNC cutting tools, 709, 709
 - in drill presses, 377–381
 - by hand, 65–66
 - on lathe, 456–457, 458
- Reaming cutting tools, 709, 709
- Reciprocating cutoff machines, 315
 - blade selection, 314–315
 - operation, 315–316
- Reciprocating saws, 302
 - safety, 304
- Recovery, recrystallization and grain growth, 223, 223
- Rectangular coordinates, CNC, 668, 669
- Regardless of feature size (RFS), 187
- Reliability
 - in measurement, 90
 - using steel rules in measurement, 107–108
- Remote gaging, 98–99, 99
- Re-sharpening milling cutters, 650–656
- Retaining rings, 24, 24
- Re-threading dies, 78, 78
- Right angle, defined, 174, 174
- Right-angle trigonometry, 177–178, 177–182
- Right-triangle solution formulas, 763
- Ring and rocker tool posts, for engine lathe, 403
- Ring gages, for taper measurement, 492–493
- Ring test, grinding wheels, 81–82, 82, 595–596, 596
- Rockwell and Brinell Hardness testers, 225–233
- Rockwell hardness tester, use, 225–231, 228
- Roller burnishing tools, 711, 711
- Roll grinding machines, 588–589, 590
- Rose reamers, 377, 378
- Rotary tables, 537, 538
 - horizontal milling machines, 564, 564
- Roughing, 277
- Roughness average (Ra), 99
- Roughness profiles, 99
- Round files, 59, 59
- Round nose pliers, 47–48, 47
- Round stock center layout, 240, 241, 497
- Roundness, defined, 88
- RPM, formula for calculation
 - drill presses, 362
 - lathes, 275, 431
 - milling machines, 530–531, 567–568
- Rule depth gages, 109–110, 109, 110
- Rule measuring instruments, 107–115
- Rules
 - applications of, in measurement, 110–111
 - care of, 110
 - decimal, 112–113, 113
 - discrimination, 107
 - flexible, 108, 108
 - hook, 108, 108, 109
 - metric, 113–114, 114
 - narrow, 108, 108
 - reading of, 111–114
 - rigid steel, 108, 108
 - short set, 108, 109
 - slide caliper, 108, 109
 - types, 108–110
- Saddles, on engine lathes, 392
- Safety
 - abrasive sawing machines, 324
 - checklist, for machines, 12
 - chip formation when turning, 442, 442
 - chip handling, 264, 387, 388, 389
 - CNC machines, 665, 666
 - cutoff machines, 304–306, 306
 - drill presses, 344–345, 345
 - federal laws, 12
 - grinding machines, 596–597, 596, 597
 - hand tools, 36
 - hot metals, 196
 - lathes, 387–390
 - machine shop, 6–13
 - milling machine, 512–513, 548
 - pedestal grinders, 82, 84
 - turning between chuck and center, 439
- Safety glasses, types of, 7, 7, 8
- Saw blades
 - blade width, 314, 314
 - gage of, 314, 314
 - kerf, 313, 314
 - materials, 313
 - pitch, 314, 314
 - saw tooth terminology, 314

- selection, 314–315
- set patterns, 314, 315
- tooth forms, 314, 314, 335, 335
- Saw teeth, set of, 54, 55, 322
- Saws
 - cold saws, 325, 325
 - safety, 306, 306
 - horizontal band saws, 302, 302, 303
 - reciprocating saws, 302
 - tilt frame band saws, 302–303, 303, 304
- Scale, defined, 107
- Scale drawings, 107
- Scale measuring instruments, 107
- Screw pitch gage, 466
- Screwdrivers
 - hollow grinding, 83, 83
 - offset, 50, 52
 - Phillips, 50, 52
 - standard blade, 50, 52
- Screws
 - cap, 17, 19
 - defined, 16
 - drive, 20, 22
 - head styles, 18
 - machine, 17, 17
 - self-tapping, 21
 - set, 18, 20
 - thread-cutting, 20, 21
 - thumbscrews, 20, 20
 - wing, 20, 20
- Screw thread micrometers, 128, 129, 479, 479
- Screw thread comparator micrometers, 125, 126
- Scribers
 - height gages, 250, 251
 - layout, 237–238, 237
- Secondary clearance angles, on milling cutters, 646, 647
- Sectioned views, on drawings, 27, 28
- Seizing, defined, 39, 40
- Selecting and identifying nonferrous metals, 203–208
- Selecting and identifying steels, 197–202
- Self tapping screws, 21
- Semiprecision layout, 244–249
- Sensitive drill presses, 342, 342, 346, 346
 - major parts of, 346, 347
- Serial taps, 68, 68
- Set screws, 18, 20
 - jack screws, 18, 20
 - points, 18–19, 20
 - square head, 18, 20
- Setup persons, 3
- Shapes, steel bars, 201, 201
- Sharp vee thread forms, 465, 466
- Sharpening drills, on pedestal grinders, 358–361
- Sharpening milling cutters, 647, 648
- Shear flow, 279, 279
- Shell reamers, 378, 378
- Shim, for keyway broach, 41–42, 42
- Shop hazards, identification of, 10–12
 - See also* Safety
- Shop presses
 - bending and straightening, 42–43
 - safety, 43
 - installing bushings, procedure for, 38–39, 39, 40
 - mandrels, 40, 40
 - types of, 37–38, 38
- Shop safety, 6–13. *See also* Safety
- Shrink fits, 185
- Side cutting pliers, 48, 48
- Side milling cutters, horizontal mill, 577–580, 580
- Silicon carbide, 598, 599
- Sine bar and gage blocks
 - for taper measurement, 493, 495
- Sine bars
 - angular measurements, 179–180, 181
 - constant tables, 181–182
- Sine ratio
 - acute angles, defined, 257
 - trigonometry, 177–182
- Single depth threads
 - external, 466, 467, 480, 481
 - internal, 483, 483
- Single-point threading, 663, 666, 689–690, 697–698
- Sinometer angle gages, 175, 176
- Sintering, 284
- Six-jaw universal chucks, for lathe, 414, 415
- Sixty-degree thread, calculations for, 465–469, 466
- Slide caliper rules, 108, 109
- Slip joint pliers, 47, 47
- Small hole gages, 148, 149, 150
- Snap gages, 91, 92
- Socket head wrenches, 50, 51
- Socket sets, 50, 50
- Socket wrenches, 50, 50
- Soft jaws, for lathe chuck, 416, 416
- Solid beam square, 152, 153
- Solid collets, for vertical mill, 521, 521
- Solid square dies, 78, 79
- Spade drills, 351, 351, 352, 709
- Spanner wrenches, types of, 50, 51
- Spark guards, pedestal grinder, 82, 82
- SPC. *See* Statistical process control
- Speeds
 - reaming, 379
 - tapping, 73–74
- Speeds and feeds
 - calculations for, 275–278
 - for machine tools, 275
- Sphericity, defined, 88
- Spheroidizing, 222, 222
- Spindle drill presses, 343, 343
- Spindle horizontal milling machines, 551
- Spindle lathe headstock, 391–392, 392
- Spindle lathes, tooling for, 413–416
- Spindle tapers
 - horizontal milling machines, 553, 554
- Spiral flute taper pin hand reamers, 64, 64
- Spiral fluted taps, 69, 69
- Spiral pointed taps, 68, 68
- Spline micrometers, 128, 128
- Spot drilling, 432–433, 433
- Spotfacing, 375–376, 376
 - defined, 29
 - symbols, 30
- Spotting drill, 351, 351

- Spring calipers, 146, 147
- Spring cleaner, for lathe, 414, 414
- Spring collets, 418, 418
- Square files, 58, 58
- Square keys, 25
- Square micrometers, 154, 155
- Squareness, defined, 89
- Squares
 - cylindrical, 153–154, 153, 154
 - diemaker's, 154, 154
 - micrometer, 155
 - precision beveled edge, 152–153, 153
 - solid beam, 152, 153
- Square threads, form of, 500, 500
- Squaring workpiece, horizontal mill, 574–576, 575, 576
- Stainless steels, 198
- Standard tolerances, 184–185
- Statistical process control (SPC), 183, 187, 189–191
 - tools for, 190–191
- Statistics, in process control, 187
- Steady rest
 - adjustment of, 496–497
 - use of, 498, 499
- Steady rest lathes, 496–499
- Steel bars, shapes, 201, 201
- Steel rules, 107–115
- Steels
 - alloy, 197
 - approximate melting points, 762
 - case hardening and tempering, 215–217
 - costs of, 202
 - heat treating, 210–213
 - identification systems, 197–198
 - pig iron, 195
 - selecting and identifying, 197–202
 - shafting, 202
 - shop tests for identifying, 199–201
 - stainless, 198
 - tool, 198–200
- Steel-spring collets, for lathe, 417, 417
- Step blocks, drill press workholding, 366, 367
- Step drills, 351
- Straddle milling, horizontal mill, 580, 580
- Straight flute hand reamers, 64, 64
- Straightness, defined, 88
- Straight peen hammers, 49, 49
- Straight pipe taps, 69, 70
- Straight shank machine reamers, 378
- Strap clamps, 366, 366, 367
 - drill press, 366, 366, 367
- Strap wrenches, 50, 51
- Stress relief anneal, 222, 222
- Stub mandrels, 444, 445, 446
- Stud bolts, 17, 17
- Subland drill, 351
- Superabrasives, 593–594
 - ratios contrasted, 625
- Supermicrometers, 98, 98
- Surface finish indicators, 99, 99
- Surface gages, 240–241
- Surface grinders, 586–588
 - accessories for, 618–619
 - chucks
 - care of, 622, 623
 - grinding-in, 626
 - setups, 623–624
 - types, 621–622, 621, 622
 - creep-feed grinding, 619
 - holding thin workpieces, 623–624
 - major parts, 617–618, 617, 618
 - nonmagnetic workpieces, 623, 624
 - odd-shaped workpieces, 623, 623
 - problems and solutions in grinding, 632–634
 - Type I surface grinder, 586–587, 587
 - Type II surface grinder, 586, 587, 587
 - Type III surface grinder, 586, 587, 587
 - use, 625–631
 - vee blocks grinding, 623, 626–631
 - workholding, 621–622, 621, 622
- Surface plates
 - grades of, 236
 - types, 236
- Surface roughness instruments, 99, 99
- Swing of engine lathe, measurement, 394
- Swiss pattern files, 59, 59

- T-bolts, 366, 367
- T-slots, machining, 535–537
- T-handle tap wrenches, 50, 52, 72, 72
- Table horizontal mill, 546, 549, 562–563, 563
- Table surface grinders, 586–587, 587
- Table vertical mills, 514, 515
- Tailstock centers, alignment, 415–450
- Tailstock chucks, 432, 432
- Tailstock engine lathes, 393–394, 394, 396–397, 397
- Tailstock turrets, engine lathe, 400, 401, 401, 402
- Tang files, 59, 61
- Tangent ratio, of acute angle defined, 257
- Tang twist drills, 350, 350
- Tantalum, 207
- Tap drills, 72–73, 73
 - size chart, 755
 - metric, 756
- Tap wrenches, 50, 52, 72, 72
- Taper bridge machine reamers, 378–379, 378
- Taper micrometers, 130, 130
- Taper milling machine arbors, 486
- Taper per foot (tpf), 485–486
- Taper pin reamers, 378, 378
- Taper pipe thread
 - American National, 468, 469
- Taper plug gages, 91, 92
- Taper ring gages, 91, 92, 492–493
- Taper shank drill sleeves, 394
- Taper taps, 67, 68
- Tapers, cutting of
 - compound slide method, 486–487
 - measurement of, 492–494
 - offset tailstock, 487–490
 - taper attachment, 490–492
 - plain taper, 490, 490, 491
 - telescoping taper, 490, 490, 491

- taper length taper portion (chart), 757
 - with angles, 758
- uses of, 485–486
- Tapers, defined, 485
- Tapping
 - CNC cutting tools, 689, 709–710
 - with drill presses, 74–76
 - by hand, 74–76
 - lathe, 458–459
 - procedures, 72–76
 - safety, 74
 - speeds, 73–74
 - tap extractors, 74, 74
 - thread depth percentage, 73
- Taps
 - Acme threads, 70, 70, 509, 510
 - blind hole defined, 68
 - bottoming, 67–68, 68
 - chamfer, 67, 67
 - drill sizes, 73
 - gun type, 68, 68
 - identifying markings, 68, 68
 - interrupted thread, 68, 68
 - major parts, 67
 - nut, 70, 70
 - pitch diameter relief, 71, 71
 - plug, 67, 68
 - pulley, 69–70, 70
 - rake and hook angles, 70, 70
 - reducing friction when using, 70–71
 - serial, 68, 68
 - spiral fluted, 69, 69
 - spiral point, 68, 68
 - straight pipe, 69, 70
 - surface treatments, 71
 - taper pipe thread, 69, 69
 - taper type, 67, 68
 - thread forming type, 69, 69
- Telescoping gages, 146–148, 147–149
- Tempering, of steels, 215–217
- Test indicators, 157, 157
- Thickness gages, 149–151, 151
 - dial type, 93, 95
- Thread cutting
 - infeed calculations, 467, 468
- Thread cutting dies, 77–80
- Thread cutting screws, 20, 21
- Thread engagement defined, 16
- Thread files, 59, 60
- Thread fit classifications, 467
- Thread forming taps, 69, 69
- Thread forms
 - Acme, 502–503, 503
 - American National, 466
 - standard taper pipe, 468, 469
 - American Standard Stub Acme, 503, 503
 - buttress, 503, 504
 - general purpose Acme, 503, 503
 - lead, defined, 504
 - metric, 16, 469, 469
 - modified square, 500, 500
 - multiple lead, 503–506
 - sharp vee, 465, 466
 - square, 500, 500
 - thread-chasing dial, 505, 505
 - UNC, 15
 - UNF, 15
 - unified, 14, 466
 - UNS, 15
- Thread grinders, 592, 593
- Thread measurement, 477–480
 - external, 477–478
 - internal, 483, 483
 - methods, 91, 92, 477–480
 - new advanced methods, 478
 - optical comparator, 480, 481
 - plug gage, 91, 92, 483, 483
 - ring gage, 91, 92, 92, 474, 477, 477
 - sharp vee form, 465, 466
 - symbols for, 31
 - three-wire method, 478–480
- Threading, on lathe, 470–475
- Threading dies, 459, 459
 - by hand, 79–80, 80
 - lathe, 483
 - types, 77–79
- Threading tools, lathe, 408–409, 409
- Threaded fasteners
 - external, 16–21
 - identification, 15
 - internal thread inserts, 21–23
 - standard series, 15, 15–16
- Threaded spindle, for lathe, 413–414, 413
- Threads
 - classes of fits for, 15
 - cutting, on lathe, 471–475
 - designations, 467
 - drawings notations, 29–30
 - fit classifications, 467
 - forms of, 14–15
 - internal inserts, 21–22, 21, 23
 - metric, 16, 751
 - per inch, measurement, 466
 - symbols on drawings, 31
 - tolerance symbols, 751–752
- Three-jaw chucks, for lathe, 414, 415, 415
- Three-square files, 59, 59
- Three-view drawings. *See* Orthographic drawings
- Tilt frame band saws, 302–303, 303, 304
- Tin, 207, 207
- Titanium, 207, 208
- Tolerance limits, 183
- Tolerance symbols, 751
- Tolerances
 - bilateral, 28
 - decimal inch notations for, 184, 752
 - defined, 28
 - effect on mating parts, 184, 184
 - geometric, 186–187
 - limit notations for, 183, 183
 - metric notations for, 184

- Tolerances (*Continued*)
 - plus-minus, 183–184
 - standard, 184–185
 - unilateral, 28
- Tool and cutter grinders
 - additional capabilities of, 656, 657
 - clearance angles, 650
 - CNC advances, 656, 658
 - cutter tooth rests for, 648, 649
 - major parts of, 645, 646
 - setup for cutter grinding, 650, 650
 - sharpening
 - cup wheel method, 651–652
 - end mills, 654–656, 655, 657
 - form-relieved cutter, 652–653, 654
 - plain milling cutter, 647, 648
 - safety, 655
 - slitting saw on, 652, 652
 - staggered-tooth cutter on, 652, 653, 654
 - straight-wheel method, 652
 - wheel abrasives for, 647–648
- Tool and die makers, 4
- Tool bit, lathe, grinding of, 410–412
- Tool breakdown, 264
- Tool length gages, CNC, 678, 678
- Toolhead vertical mill, 515, 515
 - major parts of, 514–515, 514
- Toolholders
 - carbide, identification systems for, 292, 295, 296
 - CNC machining center, 663, 663
 - engine lathe, 399–400, 399, 400
 - engine lathe tailstock, 401–404
 - milling machine, 521, 521
 - offset, 403, 403
 - straight shank, 402–403, 403
- Tooling, CNC, 705–717
- Tool rest, on pedestal grinders, 82, 82
- Toolmaker's hammers, 239, 239
- Toolmaker's microscopes, 100, 100
- Tool steels, 198–200
- Tools
 - ceramic, 288, 294, 297
 - dimensional measurement, 91–102
 - drilling, 349–357
 - hand, 45–53
 - shapes most often used, 407, 407
- Tools, cutting
 - drill press, 349–357, 350
 - horizontal milling machine, 556–561
 - lathe, 405–407
 - materials for, 284–298
 - metal-ion implantation, 520
 - vertical milling machine, 517–520, 521
- Tooth forms, for saw blades, 314, 314
- Torque wrenches, 50, 51
- Touch sensor inspections systems, 715, 715, 716
- TPI (threads per inch), 466
- Trammel points, for layout, 238, 238
- Transfer measurement, 146
- Travel error, 158, 158
- Travel indicators, 99–100, 99, 100, 106, 106
- Trepanning cutting tools, 709
- Triangles, right, 257–260
 - solution formulas, 763
- Trigonometry
 - calculations for, in layouts, 258
 - cosine ratio, 257
 - definitions, 177–179, 257
 - ratios for acute angles, 258
 - sine ratio, 177–182, 257
 - tangent ratio, 257
- Truing, of grinding wheels, 606, 607
- Tubing micrometers, 129–130, 129, 130, 138–139
- Tungsten, 208
- Turning
 - center CNC, 661, 662, 663
 - between centers, setup, 435
 - chip safety, 442, 442
 - drive (dog) plate, 435, 436
 - finishing, 443, 443
 - intermittent cuts, 441
 - to length, procedure for, 443–444, 444
 - safety, 439
 - to size, procedure for, 442–443
 - speeds and feeds, 439–441
 - tapering wear, 443
 - time for roughing and machining, 441
- Turning lathe operations, 435–437
- Turn/mill centers, 663
- Turret drill presses, 342, 343, 343
- Turret lathe tailstock, 400, 401
- Turret lathe toolpost, 401, 401, 402
- Turret lathes, 384, 385, 386
- Twist drills, 264, 264, 349–350, 349, 350, 351, 352
- Two-jaw universal chucks, for lathe, 414, 415
- Type I surface grinder, 586, 587
- Type II surface grinder, 586, 587
- Type III surface grinder, 586, 587
- Ultrasonic machining, 721, 721
- Unified external thread, cutting, 470–480
- Unified thread form, 466–467, 466
 - major parts, 14
- Unilateral tolerances, 28
- Universal bevel vernier protractors, 176–177, 176
- Universal chucks, for lathe, 414–416, 415
- Universal tool and cutter grinders. *See* Tool and cutter grinders
- Universal vise, milling machine, 537, 537
- Upright drill presses, 346–347, 348
 - heavy duty, 342, 342, 345
- User accuracy, 89
- V-anvil micrometers, 129, 129
- Vacuum chucks, for surface grinders, 622, 622
- Variables, in measurement, 91
- Vee blocks
 - defined, 42
 - drill press workholding, 369, 369
 - grinding, 623, 626–631
 - use in layouts, 243, 243, 253, 254
- Vernier
 - coincident line, 116, 117
 - principle of, 116, 117

- reliability and expectation of accuracy, 117
- shop tip, 119
- use of, 116
- Vernier bevel protractors, reading of, 177
- Vernier calipers
 - depth gage, reading of, 121
 - inch, 119, 119
 - metric, 119–121, 121
 - procedure for use, 119
 - reading of, 119–121
- Vernier height gages, 250–251
 - applications of, in layouts, 253, 253–254
 - checking zero reference, 252–253
 - discrimination and application, 116–117, 159
 - reading of, 251–252, 251–252
- Vernier micrometers, 143–144, 143
- Vertical band machines, 302, 306, 306
- Vertical band saws
 - adjusting coolant nozzle, 331–332, 332, 339, 340
 - applications of, 310, 310, 311
 - bands
 - adjusting tension, 333, 333
 - adjusting tracking, 333, 333
 - installing band guides, 330–331, 330, 331
 - selecting, 335–336, 336
 - setting velocity, 336–337, 337
 - welding, 326
 - contour sawing, 310, 310, 339–340, 340
 - friction sawing, 310, 311
 - operation, 335–340
 - other adjustments, 334, 334
 - safety, 311–312, 312
 - setting speed ranges, 337–338, 338
 - straight sawing, 338–339, 338, 339
- Vertical milling machines
 - backlash, 526
 - base and column, 514
 - climb milling, 530
 - CNC, 512, 512
 - coaxial dial indicators, 527, 527
 - conventional milling, 530
 - cutter holding on, 521, 522
 - cutting fluids for, 532–533
 - cutting speed calculations, 530–531
 - cutting tools, 517–520, 521
 - digital readout (DRO), 106, 106, 529, 529
 - face milling, 538–539
 - feed rate calculations for, 531–532
 - hole center locating, 526–527, 527
 - keyseat milling, 535, 535
 - locks, adjustment and maintenance of, 516
 - machining holes in vise body, 527–529
 - machining steps and squaring, 533
 - major parts, 514–515, 514
 - mill vise, 525–526
 - milling a cavity, 534–535
 - milling cutters, 517–520, 521
 - offset boring head, 540–543
 - operations, 530, 532, 533–539
 - plunge cutting, 533–534, 534
 - quill, 514, 515
 - ram, 514, 515
 - rotary tables, 537, 538
 - saddle, 514, 514
 - safety, 512–513
 - setups, 523–529
 - spindle on, 514, 515
 - squaring tool head, 523–524
 - standard, 512, 512
 - table, 514, 515
 - toolhead, 515, 515
 - touch-sensing probes, 527, 527
 - workholding on, 525–526
- Vertical spindle machining center
 - CNC, 663, 664, 665
- Vise body
 - machining holes in, 527–529
- Vise grip C-clamps, 48, 48
- Vise grip pliers, 48, 48
- Vises
 - care of bench, 46
 - cutaway view, 46
 - drill press work holding, 367–368, 368
 - mill, 569
 - milling machine, 563, 563
 - precision vise drawing project, 766–769
 - soft-jaw, 525, 526
 - types of, 45
 - uses of, 45–46
- Volume and capacity, measurements of, 760
- Warding files, 58, 58
- Washers
 - flat, 23, 23
 - lock, 23–24, 23
 - types, 23–24, 23
- Wear blocks, 171, 172
- Web, on twist drills, 358, 359
- Weight, measurements of, 760
- Welds, band saw blades, grinding, 329, 329, 330
- Wigglers, use in drill press, 369–370, 370
- Wire gages and metric equivalents, 764
- Wires, for thread measurement, 478–480
- Woodruff keys, 25
- Woodruff keyseat cutters, 519, 519
- Workholder turning lathe operations, 438, 439
- Workholding drill presses, 366, 367, 368–371
- Workholding grinding machines, 621–622, 621, 622
- Workholding hand tools, 45–48
- Workholding horizontal band saws, 318, 319
- Workholding horizontal mill, 562–566
- Workholding lathes, 413, 417
 - centering accuracy in inches, 418
- Workholding vertical milling machines, 525–526
- Wrenches
 - adjustable, 50, 51
 - box end, 49–50, 50
 - combination, 50, 50
 - crescent, 49, 50
 - hand tap, 50, 52
 - open-ended, 49, 50
 - pipe, 50, 51
 - safety, 53
 - socket, 50, 50

Wrenches (*Continued*)

- spanner, types, 50, 51
- strap, 50, 51
- T-handle for taps, 50, 52, 72, 72
- tap, 50, 52, 72, 72
- torque, 50, 51

- X-axis, CNC, 668, 669
- X-Y plane, CNC, 668–669, 669
- X-Z plane, CNC, 669

- Y-axis, CNC, 668, 669
- Y-Z plane, CNC, 669

- Z-axis, CNC, 668–669, 669
- Z-axis tool offsets
 - CNC, 677, 677
- Zero reference, on height gages, 252–253
- Zinc, 208
- Zirconium, 208

