

TECHNICAL INFORMATION



Revised Labor Time for Water Pump Replacement

No: 26/06/05/NAS
FGN 303-03
Ref:
Issue: 1
Date: 16 December 2005

AFFECTED VEHICLE RANGE:

Discovery Series II (LT) All

SITUATION:

PROCEDURE TIMING ERROR CORRECTED



NOTE: Associated repairs that require the new workshop procedure will also change.

An error has been discovered in the original time calculations related to the coolant pump replacement process. Although the actual process has not changed, it has been found that the original process timing included an error in timing the lower water pump fasteners. This time has now been validated and the times corrected.

RESOLUTION:

FOLLOW STANDARD WORKSHOP MANUAL PROCESURES

To remove and install the V8 coolant pump follow the procedure outlined in the WSM and referenced below.

PARTS INFORMATION:

Information only

DDW WARRANTY CLAIMS:



NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

- **Superseded repair time** 26.50.01 1.30 hours

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Time (Hours)	Condition Code	Causal Part
Replace Coolant pump	26.50.01	1.20		

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

REPLACE WATER PUMP FOLLOWING STANDARD PROCEDURE

1. Refer to GTR Workshop Manual Section 26.50.02 and replace the water pump following the steps outlined.

NOTE: The information in Technical Information bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers."
If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether the bulletin applies to a specific vehicle.

TIB	CIRCULATE:	Service Mgr	Warranty	Workshop	Body Shop	Parts
26/06/05/NAS	TO	X	X	X	X	X