



TECHNICAL ALERT

November 30, 2000

TA00 4403

NAS US Only Cda Only

ATTENTION: *General Manager* *Sales Manager*
 Service Manager *Service Advisor* *Technician*

“SE25” AT Breather Fluid Check VIN Range Extension



IMPORTANT NOTE: This Technical Alert amplifies and extends the VIN range published in Technical Alert TA00 4402 to ALL new vehicles in Retailer inventory.



NOTE: ALL new vehicles that are received into retailer inventory must be verified to be corrected and, if necessary, modified prior to sale following the procedures described in Technical Alert TA00 4402.

Vehicles discovered to have AT sump mounted breather tubes after the following VINs should be promptly reported in a Product Report to Land Rover North America and modified as per “SE25.”

- Range Rover after VIN 1A449412
- Discovery Series II after VIN 1A706116



IMPORTANT NOTE: If any contamination is found on vehicles covered by “SE25” please promptly submit a complete product report to Land Rover North America.

The service action described in Alert TA00 4402 is to be executed on all new and used vehicles in Retailer inventory prior to delivery.

No action is to be taken on vehicles that have been delivered to customers. Delivered vehicles will be addressed by the Recall bulletin where additional procedures will be outlined.

AFFECTED VEHICLE RANGE (**REVISED**)

Range Rover (LP)	XA410504 to 1A499999
Discovery Series II (LT)	XA200000 to 1A299999 XA900000 to XA907212 1A700000 to 1A799999