

TECHNICAL INFORMATION



No: 76/03/02/NAS
 Ref:
 Issue: 1
 Date: 07/26/02

Tail Door Trim Panel Vibration

AFFECTED VEHICLE RANGE:

Discovery Series II (LT) Up to 2A736340

SITUATION:

TAIL DOOR TRIM VIBRATION WHILE RADIO ON

The customer may experience a buzz or vibration when the radio is operated at medium to high volume. The original trim panel may have insufficient bonding between mating elements of the panel.

RESOLUTION:

INSTALL UPGRADED REPLACEMENT COMPONENT

Where a complaint of the above is confirmed, replace the tail door trim panel with the new panel now available from Land Rover Parts.

PARTS INFORMATION:

ESN000230LPW.....Tail door trim panel - 5 seat	Dark Smokestone
ESN000230SUC.....Tail door trim panel - 5 seat	Bahama Beige
ESN000240LPW.....Tail door trim panel - 7 seat	Dark Smokestone
ESN000240SUC.....Tail door trim panel - 7 seat	Bahama Beige
.....	

WARRANTY CLAIMS:


76.34.09.....Time 0.60 hrs.
Install replacement tail door trim
FAULT CODE: W

Normal warranty policy and procedures apply.
Material allowance is included in labor operation.

REPAIR PROCEDURE

INSTALL REPLACEMENT TAIL DOOR PANEL

1. Refer to the Discovery Series II Workshop Manual on RAVE and perform repair number 76.34.09.99.
2. Replace the tail door trim panel with the correct part for the application.



TIB 76/03/02/NAS	CIRCULATE: TO	Service Mgr X	Warranty X	Workshop X	Body Shop X	Parts X
----------------------------	-------------------------	-------------------------	----------------------	----------------------	-----------------------	-------------------