



Release Notes for the Silicon Graphics CD-RW I232 PRO Option Kit.

Please make sure you read the following before installing your CD-RW.

1. You may experience malfunctioning in the copying process if you run Direct CD before EZ CD Creator. Please run Direct CD after starting EZ CD Creator. If you see an error message such as "Cannot read data at source driver", please reinstall EZ CD Creator 4.03a update files from the Resource CD and reboot the system.
2. If EZ CD Creator or Direct CD does not recognize a used CD-RW media please erase or format it again.
3. EZ CD Creator 4.03a does not support the JustLink hardware feature on this CD-RW. To make sure you do not encounter a Buffer Underrun problem, reduce burning speed or do not run "disc at once" [CD to CD].
4. Please use ATA-66 cable.

SGI
1600 Amphitheatre Pkwy.
Mountain View, CA
94043-1351
Tel 650.960.1980

©2001 Silicon Graphics, Inc. All rights reserved. Silicon Graphics is a registered trademark and SGI and the SGI logo are trademarks of Silicon Graphics, Inc.

Document Number 007-4308-001
ACER part number 46.AB995.006 FLYER I2X CD-RW