



Customer Service

A Harman International Company

3 Oak Park Bedford, MA 01730

Tel (781) 280-0300, Fax (781) 280-0499

email: [csupport@lexicon.com](mailto:csupport@lexicon.com)

## M300 & M300L SERVICE BULLETIN

---

**SUBJECT:** Elimination of certain vendors as approved supplier for Lexicon P/N 355-07542 DAC,AD7628,CMOS,2X8BIT,MDAC

**REFERENCE:** ECO990401-00

**DISTRIBUTION:** International Pro Product Distributor Service Centers, Customer Service, Repair

**CORRECTIVE ACTION:** The following Manufacturer has been deleted from the approved vendor list for Lexicon P/N 355-07542 DAC,AD7628,CMOS,2X8BIT,MDAC: Maxim MX7628KN.

Note: the Maxim part does not always work in the M300 & M300L due to a timing violation between A/BSEL and LINWR/, RINWR/, LOUTWR and ROUTWR/ signals. Only Analog Devices parts are used in new production and should be used service failure replacements.

Please contact LEXICON CUSTOMER SERVICE with any questions.

---

sbm300&l\_990401-00.doc

Date: April 16, 1999

1