


# KENWOOD TR-751

## EXPANDED RF M/C

1. Disconnect the power and antenna.
2. Remove the case .
3. Locate the Control Unit on the radio.
4. CUT diodes D1 & D3. They are located to the left of IC3.
5. Reassemble the radio.
6. RESET the CPU. (Hold [M] key and turn on power)



DEVIATION - VR7 ON RX UNIT (OTHER SIDE)



Caution

These modifications have not been tested. The Author, Publisher and all other parties takes NO responsibility or liability for any damage or violation resulting from these modifications. Performing any modification may be a Violation of FCC Rules and will void the warranty of the radio. Use of any modified radio may be a violation of FCC rules. If you have any doubts, DO NOT PERFORM THIS MODIFICATION.

© 1991 artsci inc. all rights reserved. (818) 843-4080 Fax: (818) 846-2298