




HENRY 5K CLASSIC RF DECK - MARK II



OPERATING CONTROLS - 3K CLASSIC X Mark II and 5K CLASSIC

- |   |                               |
|---|-------------------------------|
| 1. Plate Current Meter.                   | 13. Adjustable Feet.          |
| 2. Multimeter.                            | 14. RF Output Connector.      |
| 3. Multimeter and Relay Control Switches. | 15. Cathode Fuse.             |
| 4. STANDBY Light.                         | 16. RF Input Connector.       |
| 5. POWER Light.                           | 17. ALC Connector.            |
| 6. BAND Switch.                           | 18. RELAY Connector.          |
| 7. TUNE Control.                          | 19. ALC Adjust Potentiometer. |
| 8. LOAD Control.                          | 20. Ground Stud.              |
| 9. SSB/CW Switch.                         | 21. Serial Number Tag.        |
| 10. OFF/ON Power Switch-Circuit Breaker.  | 22. Air Flow Filter.          |
| 11. AC Fuse.                              | 23. AC Power Connector.       |
| 12. AC Fuse.                              |                               |



3K&5K CLASSIC POWER SUPPLY-LOWER DECK

7/30/88

