

M300 FIELD SERVICE BULLETIN # 1

SUBJECT: M300 ANALOG BOARD, REV 4

PURPOSE: To provide the technician with troubleshooting suggestions.

CORRECTIVE ACTION: None

EQUIPMENT REQUIRED:

- 1 M300 Service Package Stk# 021-08547
- 2 M300 Diagnostic ROMs Stk# 350-08532 & Stk# 350-08533

INSTRUCTIONS:

1. Check all cables and socketed IC's for proper connection.
2. Check for cleanliness of unit.
3. Check for proper solder connections, such as fractures, insufficient solder, cold solder joints and solder bridges.

Refer to the service manual for further troubleshooting and maintenance suggestions.