

## CRW1232 Pro Software Release Notes

Read these release notes before installing the new CRW1232 Pro CD writer. Note the following:

- You must have the correct level of software that will support your new CRW1232 Pro CD writer.
- The Easy CD Creator software included with your kit must be upgraded to 4.03a or later.
- The DirectCD software included with your kit must be upgraded to 3.03a or later.
- If you are using other CD-RW software, check with the software manufacturer to ensure that there are no software compatibility problems with your software and your new CD writer.
- Software upgrades for Easy CD Creator and DirectCD are included in the resource CD-ROM (part number 153.AB997.008) that came with your SGI system.
- For the latest software upgrades, see the manufacturer's Web site at <http://www.roxio.com/en/support/ecdc/ecdcupdates.html>.

To upgrade the Easy CD Creator or DirectCD software, follow these steps:

---

**Note:** This upgrade works only on systems with previously installed Easy CD Creator 4.02 or DirectCD 3.01 software.

---

1. Insert the resource CD-ROM in the system CD-ROM drive. Click the "readme" link, and then click your system type (e.g., SGI 230).
2. Click the "ecdc\_v403a\_up.exe" or the "dcd\_v303a\_up.exe" link to upgrade the Easy CD Creator or the DirectCD software.
3. Reboot your system after the upgrade is finished.

© 2001, Silicon Graphics, Inc. All rights reserved.

SGI is a trademark of Silicon Graphics, Inc. Roxio, Easy CD Creator, and DirectCD are trademarks of Roxio, Inc. All other trademarks are the properties of their respective owners.