

**One Button Disaster Recovery (OBDR)  
For ProLiant Servers  
Tape Drive / ISV Compatibility Matrix for Current Products**

Microsoft Windows 2000					
	HP Data Protector Express 3.1 SP1A	Yosemite TapeWare 7.0 SP7D	HP Data Protector 5.5	Symantec Backup Exec 10.0	CA ARCserve 11.5
HP DAT 24 USB	√	√			
HP DAT 40	√	√	√	√	√
HP DAT 40 USB	√	√			
HP DAT 72	√	√	√	√	√
HP DAT 72 USB	√	√			
HP Ultrium 232	√	√	√	√	√
HP Ultrium 448	√	√	√	√	√
HP Ultrium 460	√	√	√	√	√
HP Ultrium 960	√	√	√	√	√
HP SDLT 600	√	√	√	√	√
HP DAT 72x6 autoloader	√	√	√	√	√

Microsoft Server 2003					
	HP Data Protector Express 3.1 SP1A	Yosemite TapeWare 7.0 SP7D	HP Data Protector 5.5	Symantec Backup Exec 10.0	CA ARCserve 11.5
HP DAT 24 USB	√	√			
HP DAT 40	√	√		√	√
HP DAT 40 USB	√	√			
HP DAT 72	√	√		√	√
HP DAT 72 USB	√	√			
HP Ultrium 232	√	√		√	√
HP Ultrium 448	√	√		√	√
HP Ultrium 460	√	√		√	√
HP Ultrium 960	√	√		√	√
HP SDLT 600	√	√		√	√
HP DAT 72x6 autoloader	√	√		√	√

Linux								
	RHEL 3		RHEL 4		SuSE 8		SuSE 9	
	HP Data Protector Express 3.1 SP1A	Yosemite TapeWare 7.0	HP Data Protector Express 3.1 SP1A	Yosemite TapeWare 7.0 SP7D	HP Data Protector Express 3.1 SP1A	Yosemite TapeWare 7.0	HP Data Protector Express 3.1 SP1A	Yosemite TapeWare 7.0 SP7D
HP DAT 24 USB			√				√	
HP DAT 40	√	√	√		√		√	
HP DAT 40 USB			√				√	
HP DAT 72	√	√	√		√		√	
HP DAT 72 USB			√				√	
HP Ultrium 232	√	√	√		√		√	
HP Ultrium 448	√	√	√		√		√	
HP Ultrium 460	√	√	√		√		√	
HP Ultrium 960	√	√	√		√		√	
HP SDLT 600	√	√	√		√		√	
HP DAT 72x6 autoloader	√	√	√		√		√	

**Notes:**

There is a known OBDR restore issue with TapeWare when the tape drive is connected to an U320 controller or embedded Smart Array 6i controller.  
Click [<here>](#) for the temporary fix until the next Service Pack is released from TapeWare

**Please Read: OBDR support by HP:**

1. HP currently supports OBDR with 5 ISVs: HP Data Protector Express, HP Data Protector, Yosemite TapeWare, Symantec Backup Exec and Computer Associates BrightStor ARCserve.
2. Yosemite TapeWare is now end of life and will no longer support new HP tape devices after December 2005.
3. Other ISVs listed as a "suitable application" have been tested by the ISV but are not supported by HP.
4. Please contact those ISVs for any disaster recovery support and OBDR support you may require.